

SBS Transit Ltd.
Bus Engineering
JR Workshop

NOTIFICATION

BUS INFORMATION

Date: 22/08/2022

Bus Number: SBS7580Y

Description: Volvo B9TL Eu5, DD, AC, 3 Axle

NOTIFICATION INFORMATION

Order # JR2208002625

OrderType: JAC1

744706.6 Km

SAP Order #

Description: Upper deck front windscreen cracked. ON 22AUG2022 AT EST 1515HR BEFORE 14.2KM TOWARDS EUNOS (SIM HQ) ALONG CLEMENTI ROAD. BC CLAIMS PRIVATE HIRE CAR CUT INTO HIS LANE, AND BC EBRAKE.

Reported By: 17802

Reported Date/Time: 22/Aug/2022 17:32

Notification Status: 05R Minor Accident (Repair < 16 hours)

NOTIFICATION DETAILS

S/N Symptom Description

Remarks:

RTD after consult with CRS. SV154, 14.2KM BC CLAIMS HE HEARD A LOUD SOUND, AND MOVED TO THE BUS STOP AHEAD. BC WENT UP TO CHECK AND REALISED UPPER DECK FRONT WINDSCREEN CRACKED. STEERING AND BRAKES ALL OK.

BC Name & Signature: 17802

Date: 22/8/22

Surveyor: Rasul

Hp 90010068

1 day

29/08/22 @ 0900

Reply to after repair

email: rasul@kkauto.com