



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref : UC500
Vehicle No. : SJH7723R
Make & Model : HONDA STREAM 1.8

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Side mirror LH <i>scr</i>		587.00	3035 20% 2428
1	Front door LH <i>scr</i>		984.00	
1	Front door lock LH <i>? H</i>		237.00	
1	Front door window regulator LH <i>X n</i>		444.00 X	
1	Front door tape <i>re</i>		49.00	
1	Front door outer handle LH <i>? scr</i>		133.00	
1	Rear door LH <i>scr</i>		958.00	
1	Rear door hinge upper LH <i>bt</i>		45.00	
1	Rear door hinge lower LH <i>X n</i>		45.00 X	
1	Rear door checker LH <i>X n</i>		49.00 X	
1	Rear door run channel LH <i>X n</i>		51.00 X	
1	Rear door vertical garnish <i>X n</i>		36.00 X	
1	Rear door tape <i>scr</i>		42.00	
1	Rear fender LH (Repair refer to labour)		0.00	
1	B pillar (Repair refer to labour)		0.00	
1	Rocker panel (Repair refer to labour)		0.00	
Part Items Total:			3660.00	
			-20%	
			-732.00	
			2928.00	
SPECIAL NETT ITEMS				
1	Rain shield tape <i>scr</i>		50.00	30 30
SN Items Total:			50.00	
Total Parts:			2978.00	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC500
Vehicle No. : SJH7723R
Make & Model : HONDA STREAM 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500 400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800 500
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	90.00	60
4	To perform anti-rust treatment on affected areas	60.00	
5	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	80 60
6	To remove and refit/replace Rear door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	60
Labour Total :		2390.00	
TOTAL (PARTS & LABOUR):		5268.00	5634.40

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2428.00

30.00

266.40

1540.00

4264.40

20%

3411.52

45-\$3,400/5days

Repair

HP 90010068

5 days

L/S

26/08/22 P1220

Reg after repair

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1410
Vehicle No. : SJH7723R
Make & Model : HONDA STREAM 1.8

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>					
1	Rear Door outer handle LH <i>scr</i>	<i>333</i> <i>20%</i> <i>266.40</i>	133.00		
1	Rear Door Glass window Sliding bracket LH <i>bt</i>		200.00		
			333.00		
			-20% 33.30	66.60	
			266.00	266.40	
<u>SPECIAL NETT ITEMS</u>					
<u>LABOUR</u>					
1					
Total Parts			366.30	266.40	