

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008287/UVY3E2**Date:** 18/11/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 1001982764 |
| Claimant Vehicle No : | SJL5080D | Insured Vehicle No : | SKN9800U |
| Date of Loss: | 23/08/2022 | Nature of Claim: | TP |
| | | Claim No: | 283320 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SJL5080D | Engine No: | 1NZD130614 |
| Make & Model: | TOYOTA SIENTA, 1.5 X LIMITED (A) | Chassis No: | NCP815066765 |
| Reg. Date: | 28/11/2008 (Man. Year: 2008) | Odometer: | 150046 km |
| Colour: | Silver | | |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 195/60 R15 | Rear Tyre Size: | 195/60 R15 |
| Front Left Side: | LAUFENN 6 mm | Rear Left Side: | LAUFENN 6 mm |
| Front Right Side: | LAUFENN 6 mm | Rear Right Side: | LAUFENN 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 5,294.90 | 716.52 | 4,578.38 | 86.47 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,660.00 | 460.00 | 3,200.00 | 87.43 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,954.90 | 1,176.52 | 7,778.38 | 86.86 |
| Approved Total (Overridden) (S\$) | | 900.00 | | |
| Nett Amount (S\$) | 8,954.90 | 900.00 | 8,054.90 | 89.95 |

INSPECTION

| | | |
|-----------------------------|------------|--------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 29/08/2022 | |
| Date Inspected: | 29/08/2022 | Inspected At: Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339 Singapore 470130 |
| Estimated Period of Repair: | 2.0 days | |

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 14 Nov 2022) |
| Parts: | M1-MPV | TOYOTA SIENTA 1.5 X LIMITED (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJL5080D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|------------|
| 1 | 1 | | *REAR FENDER - LH | Not Necessary | 1,270.50 FL | *- FL |
| 2 | 1 | | *REAR FENDER INNER SHIELD | Not Necessary | 160.70 FL | *- FL |
| 3 | 1 | | *REAR BUMPER | Deformed | 888.70 FL | *888.70 FL |
| 4 | 1 | | *REAR BUMPER REFLECTOR | Not Necessary | 95.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER | Not Necessary | 64.40 FL | *- FL |
| 6 | 1 | | *REAR WHEEL HUB WITH BEARING | Not Necessary | 571.80 FL | *- FL |
| 7 | 1 | | *REAR SHOCK ABSORBER | Not Necessary | 186.50 FL | *- FL |
| 8 | 1 | | *REAR AXLE BEAM | Not Necessary | 1,895.60 FL | *- FL |
| 9 | 1 | | *SET REAR BUMPER CLIP | Necessary | 50.00 FS | *50.00 FS |
| 10 | 1 | | *SET REAR FENDER INNER SHIELD CLIP | Not Necessary | 45.00 FS | *- FS |
| 11 | 1 | | *REAR TYRE | Serviceable | 400.00 FS | *- FS |
| 12 | 1 | | *REAR WHEEL RIM - LH | Repair | 950.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|------------------------------------------------------------|-----------------|---------------|
| Sub Total (\$\$) | 6,578.20 | 938.70 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,283.30 | 222.18 |
| Total Parts (\$\$) | 5,294.90 | 716.52 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|-----------------------------------------------------------|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE, REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING | New | 80.00 | 0.00 |
| 2 | TO REMOVE AND REFIT INNER GARNISHES | New | 180.00 | 0.00 |
| 3 | TO REMOVE AND REFIT REAR UNDERCARRIAGE | New | 250.00 | 0.00 |
| 4 | TO CONDUCT WHEEL ALIGNMENT | New | 150.00 | 60.00 |
| 5 | TO APPLY UNDERCOATING | New | 100.00 | 0.00 |
| 6 | PANEL BEATING | New | 1,500.00 | 200.00 |
| 7 | TO RE-SPRAY PAINTING ON THE AFFECTED AREAS | New | 1,400.00 | 200.00 |
| Gross Labour Cost (S\$) | | | 3,660.00 | 460.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >