

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008288/KNY3E2**Date:** 06/01/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001960148

Claimant Vehicle No : SMY81E**Insured Vehicle No :** SLK2240K

Date of Loss: 25/08/2022

Nature of Claim: TP

Claim No: 283107

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY81E**

Make & Model: NISSAN NOTE E-POWER, 1.2 L PREMIUM (A)

Engine No: HR12288853K

Reg. Date: 30/06/2021 (Man. Year: 2021)

Chassis No: JN1FAAE13Z0900295

Colour: Metallic Orange

Odometer: 42350 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R16

Rear Tyre Size: 185/60 R16

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,131.81	1,982.11	1,149.70	36.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,400.00	480.00	25.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,011.81	3,382.11	1,629.70	32.52
+ GST 7.00/7.00% (S\$)	350.83	236.75	114.08	32.52
Nett Amount (S\$)	5,362.64	3,618.86	1,743.78	32.52

INSPECTION

Date of Assignment: 29/08/2022

Date Inspected: 12/09/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	144	NISSAN NOTE E-POWER 1.2 L PREMIUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY81E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	562.50 FL	*562.50 FL
2	1		*REAR BUMPER SPONGE	Serviceable	138.00 FL	*- FL
3	1		*REAR BUMPER TOW HOOK COVER	Serviceable	29.00 FL	*- FL
4	6		*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
5	1		*REAR TAILGATE	Bent	1,312.20 FL	*1,312.20 FL
6	1		*TAILGATE INNER RUBBER	Serviceable	110.30 FL	*- FL
7	1		*TAILGATE INNER LOCK	Repair	138.70 FL	*- FL
8	1		*TAILGATE EMBLEM NOTE	Necessary	151.60 FL	*151.60 FL
9	1		*TAILGATE EMBLEM E POWER	Necessary	101.60 FL	*101.60 FL
10	1		*REAR END PANEL	Repair	660.00 FL	*- FL
11	1		*REAR END PANEL INNER TOP GARNISH	Serviceable	82.00 FL	*- FL
12	1		*REAR END PANEL ANTENNA	Serviceable	75.00 FL	*- FL
13	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
14	1		*REAR END PANEL SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,470.90	2,197.90
- List Item Discount on L Items 10.00/10.00% (S\$)	339.09	215.79
Total Parts (S\$)	3,131.81	1,982.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE & ATTACHMENTS, TAILLAMPS. TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	New	850.00	600.00
3	PUTTY & RESPRAY REAR BUMPER & ATTACHMENTS, TAILGATE, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	New	800.00	600.00
4	REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	New	50.00	50.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,880.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >