

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS3/SMO22005032/Kvy3e2-1	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	02/09/2022	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMJ 9008M	Veh. Inspected	SNA 8708T	
	Policy No.	D21MTPV01008878	Coverage (\$)	0.00	
	Claim No.	CMTD2201596/GPL	Excess (\$)	0.00	
	Assign From	GNOH PAU LOONG	Assign Date	26/08/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 KOMPRESSOR	c.c	1597	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	WDD2040452A632956	Colour	METALLIC SILVER	
	Odometer	193737 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/05/2022	Inspection Date	30/05/2022	
	Survey held at	MING HUA AUTO SERVICES			
		160 SIN MING DRIVE #02-16 SIN MING AUTO CITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	21 Wor	king Days	