

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: ALLIANZ	DATE	: 19/08/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
VEHICLE DETAILS			
VEHICLE NO	: SMT9841X	<i>Xiao Tony.</i> WDC1569422J680243	
MODEL	: MERCEDES BENZ GLA180		
CHASSIS NO			
ACCIDENT DETAILS	DATE : 18-Aug-22		
	TIME : 18:20HRS		
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,055.60	\$ 2,055.60
2	TAILGATE LOGO	1	\$ 92.50	\$ 92.50
3	TAILGATE EMBLEM 'GLAI' <i>new</i>	1	\$ 66.30	\$ 66.30
4	TAILGATE EMBLEM '180'	1	\$ 54.80	\$ 54.80
5	TAILGATE LAMP <i>cut</i>	1	\$ 560.50	\$ 560.50
6	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 182.20	\$ 182.20
7	REAR BUMPER <i>Dented</i>	1	\$ 1,588.20	\$ 1,588.20
8	REAR BUMPER SIDE RETAINER <i>LH Dented</i>	2	\$ 140.20	\$ 280.40
9	REAR BUMPER CHROME <i>new</i>	1	\$ 266.30	\$ 266.30
10	REAR BUMPER INNER GARNISH <i>new</i>	1	\$ 311.20	\$ 311.20
11	REAR BUMPER DIFFUSER <i>Dented</i>	1	\$ 820.00	\$ 820.00
12	REAR BUMPER LOWER LID <i>Dented</i>	1	\$ 1,055.20	\$ 1,055.20
13	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 710.00	\$ 710.00
14	REAR BUMPER SIDE BRACKET <i>LH and</i>	2	\$ 130.00	\$ 260.00
15	TAILLAMP <i>cut</i>	1	\$ 833.50	\$ 833.50
16	REAR FENDER WHEEL ARCH LH <i>new</i>	1	\$ 280.50	\$ 280.50
17	REAR EXHAUSE PIPE <i>new</i>	1	\$ 1,822.60	\$ 1,822.60

✓
✓
✓
✓
✓
✓
1386
140.20
✓
\$55
645.
+ 130
✓
+

18	REAR EXHAUSE PIPE INSULATOR <i>new</i>	1	\$ 222.30	\$ 222.30
19	REAR EXHAUSE PIPE CHROME LH <i>Dented LH</i>	2	\$ 411.50	\$ 823.00
20	REAR EXHAUSE PIPE BRACKET <i>new</i>	2	\$ 255.90	\$ 511.80
21	REVERSE SENSOR <i>LH Rnd</i>	2	\$ 320.50	\$ 641.00

898560 TOTAL PRICE \$ 13,437.90
 808704 LESS 10% \$ 1,343.79
SUB TOTAL PRICE \$ 12,094.11

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 22.00	\$ 22.00

22 TOTAL \$ 72.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,400.00	500	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,400.00	500	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	X	
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
7	TO TRANSFER REAR WINDSCREEN	\$ 140.00	120	
8	TRANSFER BOOTLID MECHANISM	\$ 120.00	60	
9	DIAGNOSTICS REVERSE SENSOR AND DISTANCE SETTING	\$ 160.00	50	
10	TO REMOVE AND REFIX REAR EXHAUST PIPE	\$ 280.00	X	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO	\$ 350.00	X	

TOTAL \$4,550.00

1300

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,166.11
 TOTAL LABOUR COS : \$ 4,550.00
 TOTAL REPAIR COS : \$ 16,716.11

APPROVED DETAILS

SURVEYOR :

CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS

FAX :

Adrian Lj
n/s 23/08/22.
05 Days

total: 9409.04
n/s: 7.5k

7.5k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: