

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22008294/AYA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SJE7377Y**Insured Vehicle No :** SLU1870X

Date of Loss: 18/08/2022

Nature of Claim: TP

Claim No: MFL2022D0004557

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJE7377Y**

Make & Model: TOYOTA RUSH, 1.5 X (A)

Engine No: 3SZ2028143

Reg. Date: 06/05/2008 (Man. Year: 2008)

Chassis No: J200E0019538

Colour: Black

Odometer: 261458 km

Engine Capacity: 1495 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Kinforest 6 mm

Rear Left Side: Kinforest 6 mm

Front Right Side: Kinforest 6 mm

Rear Right Side: Kinforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,766.12	2,379.15	2,386.97	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,250.00	1,950.00	60.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,966.12	3,629.15	4,336.97	54.44
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	7,966.12	2,900.00	5,066.12	63.60
+ GST 8.00/8.00% (S\$)	637.29	232.00	405.29	63.60
Nett Amount (S\$)	8,603.41	3,132.00	5,471.41	63.60
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,499.45		

INSPECTION

Date of Assignment: 22/08/2022

Date Inspected: 23/08/2022 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts:	M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE7377Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,588.30 FL	*1,112.00 FL
2	1		*REAR FENDER RH	Repair	1,120.50 FL	*- FL
3	1		*REAR BUMPER	Torn	650.20 FL	*650.20 FL
4	1		*REAR BUMPER RETAINER	Cracked	102.50 FL	*50.00 FL
5	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
6	1		*REAR WHEEL RIM	Cut	800.00 FS	*500.00 FS
7	1		*REAR WHEEL TYRE	Not Necessary	350.00 FS	*- FS
8	1		*BUILD UP SPOILER BODYKIT	Cut	1,000.00 FS	*500.00 FS
					Sub Total (\$\$)	5,631.50 2,832.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	865.38 453.05
					Total Parts (\$\$)	4,766.12 2,379.15

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	150.00	30.00
5	TRANFER REAR DOOR MECHANISM	New	180.00	60.00
6	REMOVE AND REFIX REAR SENSOR SETTING	New	100.00	50.00
7	FOUR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			3,200.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >