

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA	DATE	: 19/08/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJE7377Y		
MODEL	: TOYOTA RUSH 1.5A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 18-Aug-22
		TIME	: 17:15HRS
THIRD PARTY REQUESTOR / CONTACT : MS HONG / SHARON			

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH	1	\$ 1,588.30	\$ 1,588.30
2	REAR FENDER RH	1	\$ 1,120.50	\$ 1,120.50
3	REAR BUMPER	1	\$ 650.20	\$ 650.20
4	REAR BUMPER RETAINER	1	\$ 102.50	\$ 102.50

TOTAL PRICE	\$	3,461.50
LESS 25%	\$	865.38
SUB TOTAL PRICE	\$	2,596.13

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS	1	\$ 20.00	\$ 20.00
2	REAR WHEEL RIM	1	\$ 800.00	\$ 800.00
3	REAR WHEEL TYRE	1	\$ 350.00	\$ 350.00
4	BUILD UP SPOILER BODYKIT	1	\$ 1,000.00	\$ 1,000.00

TOTAL	\$	2,170.00
--------------	-----------	-----------------

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00		
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00		
3	TUFF COAT	\$ 250.00		
4	WIRING CHECK	\$ 150.00		
5	TRANSFER REAR DOOR MECHANISM	\$ 180.00		
6	REMOVE AND REFIX REAR SENSOR SETTING	\$ 100.00		
7	FOUR WHEEL ALIGNMENT	\$ 120.00		

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	4,766.13
TOTAL LABOUR COST	:	\$	3,200.00
TOTAL REPAIR COST	:	\$	7,966.13

APPROVED DETAILS

SURVEYOR :

CONTACT NO : FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :