

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Xiao Tong

Estimate Quotation

Quotation No	Aug 003/2022
Date	19/8/2022
Vehicle No	SLT737K
Make / Model	Mazda 5

To: AIG Asia Pacific Insurance Pte Ltd
Address: 78 Shenton Way #07-16 Singapore 079120

JM6CW107114 0126609

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Deformed</i>		\$ 1,355.00 <i>1082</i>
1 pc	front bumper lower grille <i>Cracked</i>		\$ 258.00
1 pc	front number plate frame <i>new</i>		\$ 50.00 <i>+</i>
1 set	front bumper side retainer <i>new</i>		\$ 63.00 <i>+</i>
1 pc	o/s headlamp <i>Cracked</i>		\$ 1,779.00
1 pc	o/s fog lamp <i>new</i>		\$ 415.00 <i>+</i>
1 pc	o/s fog lamp garnish <i>Cracked</i>	<i>4602</i>	\$ 96.00 <i>+</i>
1 pc	bonnet <i>Dented</i>		\$ 1,350.00 <i>1032</i>
1 pc	bonnet protector <i>new</i>		\$ 150.00 <i>+</i>
1 pc	front grille <i>new</i>		\$ 355.00 <i>✓</i>
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair	<i>960</i>	\$ 800.00 <i>500</i>
2	to putty and spray painting on affected area		\$ 1,000.00 <i>400</i>
3	anti rust		\$ 50.00 <i>30</i>
4	wiring check		\$ 80.00 <i>30</i>
Subtotal:			\$ 7,801.00

*Admin C
2/S 2A/08/22
04 days*

BEST SOLUTION AUTOCARE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorised Signature

*total: 4641.60
2/S: 3.71C ✓*