

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : TAN WEI LOONG WILSON

Vehicle No : SJY 419 B

Make/Model : AUDI A5

Accident date : 16.08.2022

TPA 16.
Asker.

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Front RH fender <i>Dented</i>	1	\$ 1,449.60 <i>1208.</i>
2	Front RH door <i>Dented.</i>	1	\$ 3,666.00 <i>3155</i>
3	Front RH door top hinge <i>3 new</i>	1	\$ 201.60 <i>x</i>
4	Front RH door lower hinge <i>new</i>	1	\$ 201.60 <i>x</i>
5	Front RH door stopper <i>new</i>	1	\$ 430.80 <i>x</i>
6	Front RH door weather strip <i>new</i>	1	\$ 562.80 <i>469.</i>
7	Rocker panel <i>new</i>	1	\$ 2,220.00 <i>x</i>
8	Rear fender inner shield <i>new</i>	1	\$ 280.00 <i>x</i>
		Total	\$ 9,012.40

Labour Cost

1 Remove & reinstall door glass	910	\$	150.00	80
2 Remove ,replace & repair consistent to the accident		\$	1,000.00	400
3 Respray painting		\$	1,000.00	400
4 Tuff kote		\$	100.00	30
	Total	\$	2,250.00	

Grand Total \$ 11,262.40

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

total: 5258.80
L/S: 4.2K.
04 Days