

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJR 371RYr Regn: 5/6/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fitc.c. 1339Colour: Red

A/C: Insured / Std / Nil / NA

Sp. Reading 166076

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: GL 61158378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or .

Front

Rear

R/Bal. 4

mm

R/Bal. 4

mm

L/Bal. 4

mm

L/Bal. 4

mm

D.O.A. 23/8/12D.O.I. 7/9/12Survey held at ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-17K

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

ARC**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2208-453-TG

DATE : 24-Aug-2022

POLICY NO. : P10738877R00

VEHICLE REG. NO. : SJR371R

VEHICLE MAKE : HONDA / FIT 1.3G A 2009

GE61158328

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / BR	1	\$ 995.00	\$ 995.00
2	Rear Bumper Clips / RC	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH / BR	1	\$ 33.00	\$ 33.00
4	Rear Bumper Retainer LH / BR	1	\$ 33.00	\$ 33.00
5	Rear Tailgate / DM	1	\$ 1,100.00	\$ 1,100.00
6	Rear Tailgate Lock	1	\$ 180.00	\$ 180.00
7	Rear Tailgate Door Weatherstrip / TN	1	\$ 200.00	\$ 200.00
8	Rear Tailgate Door Inner Trim	1	\$ 130.00	\$ 130.00
9	Rear Tailgate Door Garnish / X	1	\$ 140.00	\$ 140.00
10	Rear Windscreen Moulding Assy / RC	1	\$ 150.00	\$ 150.00
11	Rear End Panel	1	\$ 553.00	\$ 553.00
12	Rear End Panel Garnish / CPU	1	\$ 170.00	\$ 170.00
Total Spare Parts				\$ 3,734.00
SPECIAL NETT				
13	Rear License Plate With Casing / X	1	\$ 40.00	\$ 40.00
14	Rear Windscreen Sealant / RC	1	\$ 60.00	\$ 60.00
15	Reverse Sensor / SHW	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 300.00
LABOUR				
16	Spray Paint RrBumper, Tailgate, Blend RrFenderRH&LH	1	\$ 800.00	\$ 400 800.00
17	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 600.00	\$ 400 600.00
18	Transfer Tailgate Fitting And Window Mechanism to New	1	\$ 100.00	\$ 50 100.00
19	Remove and Install Rear Windscreen	1	\$ 100.00	\$ 100.00
20	Remove & Refit Rear Reverse Sensor	1	\$ 100.00	\$ 30 100.00
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 30 100.00
22	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,830.00
Amount Before Excess				\$ 5,864.00
Add GST @ 7%				410.48
Total Amount Payable				\$ 6,274.48

Estimate prepared by: RAZALI

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before repair work commencing
- To display damaged parts during resurvey
- Parts quotation on parts and labour are current and subject to change.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: