

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2208-453-TG
DATE : 24-Aug-2022
POLICY NO. : P10738877R00
VEHICLE REG. NO. : **SJR371R**
VEHICLE MAKE : HONDA / FIT 1.3G A 2009
GE61158328**TO** Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033**FOR SURVEYOR****ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 995.00	\$ 995.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 33.00	\$ 33.00
4	Rear Bumper Retainer LH	1	\$ 33.00	\$ 33.00
5	Rear End Panel	1	\$ 553.00	\$ 553.00
6	Rear End Panel Garnish	1	\$ 170.00	\$ 170.00
Total Spare Parts				\$ 1,834.00
	<u>SPECIAL NETT</u>			
7	Rear License Plate With Casing	1	\$ 40.00	\$ 40.00
8	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
	<u>LABOUR</u>			
9	Spray Paint RrBumper,Tailgate,Blend RrFenderRH&LH	1	\$ 800.00	\$ 800.00
10	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 600.00	\$ 600.00
11	Repair Tailgate	1	\$ 200.00	\$ 200.00
12	Remove & Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
13	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
14	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,830.00
Amount Before Excess				\$ 3,904.00
Add GST @ 7%				273.28
Total Amount Payable				\$ 4,177.28

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.