

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

30/8/2022

M/S. AIG

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA DYNA - GBJ2184M

DOA : 23/08/2022

Not Allowed
1/9/22
P/P \$2910
3 days

S/N QTY DESCRIPTION

TO SUPPLY & RE-WRAP PASSENGER SIDE REAR
SWING DOOR

TO SUPPLY AND REPLACE REAR STEP
TO MAKE GOOD REAR SWING DOOR BRACKET
TO RE-ADJUST REAR SWING DOOR ALIGNMENT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

labour for panel beating & replacing parts — 500 — 400
To putty & spray painting — 200 — 100
To R & R rear reverse sensor — 50 — 11X

S/Nett item

1PC	Rear cargo box door NS	\$1200	-	900	NS	—
1PC	Rear cargo box door OS	\$1200	-	900	OS	—
1PC	Rear cargo box lower member	\$600	-		R X	
1PC	Rear step panel assy	\$800	-	600	Suf	
1PC	Rear licence plate	\$20			su X	
1PC	Rear licence plate bracket	\$115			R X	
1set	Rear reverse sensor	\$200			su X	
1PC	70 km/h sticker	\$10			su ✓	

P. 2410