

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NINA LOO SWEE LENG
BLK 8 JOO SENG ROAD #07-02
SINGAPORE 360008

Contact : 96975063

TP Alhaz
Ashes

TAX INVOICE

Repair Code : CLM15629

Date in : 23/08/2022

Vehicle Num. : SKB460P

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104114394/1ZRX080008

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Buckled</i>	1	925.40	<i>754</i> 925.40
REAR BOOTLID '1.6' EMBLEM <i>3</i>	1	35.80	35.80
REAR BOOTLID 'ALTIS' EMBLEM <i>1</i>	1	49.10	49.10
REAR BOOTLID 'COROLLA' EMBLEM <i>1</i>	1	49.10	49.10
REAR BOOTLID 'DUAL' EMBLEM <i>2</i>	1	39.20	39.20
REAR BOOTLID 'LOGO' EMBLEM <i>1</i>	1	61.60	61.60
REAR BOOTLID 'VVT-I' EMBLEM <i>1</i>	1	43.10	43.10
REAR BOOTLID HINGES L/R <i>2</i>	2	68.70	<i>+</i> 137.40
REAR BOOTLID LH REFLECTOR LAMP <i>2</i>	1	175.80	175.80
REAR BOOTLID LH REFLECTOR LAMP GASKET SEAL <i>1</i>	1	29.80	29.80
REAR BOOTLID MECHANISM LOCK <i>1</i>	1	111.80	<i>+</i> 111.80
REAR BOOTLID RUBBER GUIDE STOPPER <i>4</i>	4	10.00	<i>+</i> 40.00
REAR BOOTLID WEATHER STRIP <i>1</i>	1	194.20	194.20
REAR BUMPER <i>Deformed</i>	1	556.40	556.40
REAR BUMPER CORNER RETAINER L/R <i>2</i>	2	34.80	<i>+</i> 69.60
REAR BUMPER LH BRACKET <i>Dented</i>	1	92.00	92.00
REAR BUMPER LH END SEAL COVER <i>2</i>	1	49.30	<i>+</i> 49.30
REAR BUMPER LH REFLECTOR <i>1</i>	1	39.30	39.30

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NINA LOO SWEE LENG
BLK 8 JOO SENG ROAD #07-02
SINGAPORE 360008

Contact : 96975063

TAX INVOICE

Repair Code : CLM15629

Date in : 23/08/2022

Vehicle Num. : SKB460P

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104114394/1ZRX080008

REAR BUMPER SIDE RETAINER L/R	LH Dented	2	72.90	72.90	145.80
REAR BUMPER SPONGE	cracked	1	142.60	✓	142.60
REAR END PANEL	Dented	1	670.00	✓	670.00
REAR END PANEL INNER TOP GARNISH	Rehnd	1	213.80	✓	213.80
REAR LH FENDER INNER UPHOLSTERY TRIM	Neu	1	370.30	+	370.30
REAR LH TAILLAMP	cracked	1	375.50	✓	375.50
REAR LH TAILLAMP GASKET SEAL	Neu	1	35.20	✓	35.20
REAR LH TAILLAMP LOWER BRACKET	Neu	1	80.70	+	80.70
REAR SPARE TYRE INNER TOP UPHOLSTERY BOARD	form	1	294.50	✓	294.50
Subtotal before discount					5,027.30
Percentage discount 25%					1,256.83
Sub-total 1					3,770.48
REAR BOOTLID CHROME MOULDING CLIPS - SET	Neu	1	30.00	+	30.00
REAR BUMPER CLIPS - SET	Neu	1	50.00	30	50.00
REAR BUMPER END COVER CLIPS - SET	Neu	1	30.00	+	30.00
REAR BUMPER REVERSE SENSOR	Neu	1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	Neu	1	30.00	10	30.00
REAR END PANEL SEALANT	Neu	1	80.00	60	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Rukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

NINA LOO SWEE LENG
BLK 8 JOO SENG ROAD #07-02
SINGAPORE 360008

Contact : 96975063

TAX INVOICE

Repair Code : CLM15629

Date in : 23/08/2022

Vehicle Num. : SKB460P

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104114394/1ZRX080008

REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET	<i>new</i>	2	30.00	<i>+</i>	60.00
REAR TAILLAMP CLIPS L/R - SET	<i>M</i>	2	20.00	<i>10</i>	40.00
Subtotal before discount					570.00
Percentage discount 0%					0.00
Sub-total 2					570.00
Parts-total					4,340.48

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,460.00
Parts & Labour Total	6,800.48

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
h/s 26/08/22
26 days
total: 5032.92
L/S: AK ✓