

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

Not Authorised
2/5 \$
Pdyr.

25/8/2022

M/S LONPAC INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR MERCEDES B200 - SKK5374A

DOA : 25/08/2022

S/N	QTY	DESCRIPTION		
1	1 PC	FRT BONNET	5mt ✓	
2	1 PC	FRT HEADLAMP - RH	5mt ✓	
3	1 PC	FRT GRILLE	1mt ✓	
4	6 PCS	FRT GRILLE CHROME GARNISH	?	
5	1 PC	FRT BUMPER	Dis ✓	
6	1 PC	FRT BUMPER TOW COVER	11 X	
7	3PCS	FRT BUMPER PARKING SENSOR	shut 1pc	
8	1 PC	FRT BUMPER WASHER JET COVER - RH	1mt ✓	
9	1 PC	FRT BUMPER SIDE RETAINER - RH	1mt ✓	
10	1 PC	FRT BUMPER LOWER AIR GRILLE	11 X	
11	1 PC	FRT HEADLAMP WASHER JET NOZZLE - RH	?	
12	1 PC	FRT HEADLAMP WASHER JET NOZZLE MOTOR - RH	?	
13	1 PC	FRT BUMPER RH LOWER GRILLE	11 X	
14	1 PC	FRT BUMPER RH LWR GRILLE OUTER CHROME GARNISH	?	
15	1 PC	FRT BUMPER RH LOWER GRILLE FOG LAMP	?	
16	1 PC	FRT BUMPER RH GRILLE LOWER CHROME GARNISH	mt ✓	
17	1 PC	ENGINE UNDERCOVER	70-11 ✓	
18	1 PC	FRT RH FENDERSHIELD	11 X	
19	1 PC	FRT RH FENDERSHIELD CLIPS	11 X	
20	1 PC	SUPPORT PANEL	?	
21	1 PC	FRT NUMBER PLATE	11 X	S.NETT
22	1 PC	REAR WS MOULDING	yes ✓	
23	1 PC	REAR TAILGATE	no ✓	
24	1 PC	REAR TAILGATE "MERCEDES" EMBLEM	yes ✓	
25	1 PC	REAR TAILGATE "B200" EMBLEM	yes ✓	
26	2PCS	REAR TAILGATE RED REFLECTOR	2/5 1mt 1pc	
27	1 PC	TAILGATE LOCK	no/shut ✓	
28	1 PC	TAILGATE TRIM BOARD (LOWER PART)	11 X	
29	1 PC	REAR BUMPER	Dis ✓	
30	2PCS	REAR TAIL LAMP (OUTER)	?	
31	4PCS	REAR BUMPER REVERSE SENSOR	shut 2pcs	

32	1 PC	REAR BUMPER LOWER	D.S. —		
33	2 PCS	REAR BUMPER SIDE CHROME GARNISH	ner —		
34	1 PC	REAR BUMPER TOW COVER	17X		
35	1 PC	REAR BUMPER REINFORCEMENT	berl —		
36	1 PC	REAR BUMPER SIDE RETAINER LH	berl —		
37	1 PC	REAR BUMPER TOP CHROME GARNISH	ner —		
38	1 PC	REAR EXHUAUST MUFFLER BOX	berl —		
39	1 PC	REAR EXHUAUST MUFFLER ALUMINIUM COVER	ner —		
40	1 PC	END PANEL	?		
41	1 PC	SPARETYRE PANEL	2x	REPAIR	
42	10 PCS	REAR BUMPER CLIPS	ner 50	S.NETT	\$ -
43	1 PC	REAR NUMBER PLATE	ner 40	S.NETT	\$ -

	FRONT LABOUR:		\$ 150.00	400?
44	DIAGNOSE AIRBAG LIGHT - DASHBOARD		\$ 35.00	✓
45	SPRAY PAINTING		\$ 880.00	600
46	REMOVE AND REFILL AIRCON GAS		\$ 160.00	17X
47	WIRING		\$ 50.00	20
48	TUFF COAT		\$ 400.00	60
49	LABOUR CHARGE		\$ 960.00	500
	REAR LABOUR :			
50	LABOUR CHARGE		\$ 1,100.00	800
51	SPRAY PAINTING		\$ 1,000.00	900
52	REMOVE AND REFIX REAR WINDSCREEN		\$ 120.00	✓
53	REAR WINDSCREEN SEALANT		\$ 25.00	✓
54	TUFF COAT		\$ 80.00	50
55	WIRING		\$ 50.00	20
56	LABOUR FOR REVERSE SENSOR		\$ 80.00	50
Total				