

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

Acknowledged by Repairer

Signature:

Date:

M/S LONPAC INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR MERCEDES B200 - SKK5374A (DOA 25/8/22)

S/N	QTY	DESCRIPTION	LIST PRICE
1	1 PC	FRT BONNET BT -	\$ 1,840.00
2	1 PC	FRT HEADLAMP - RH BRU -	\$ 2,975.00
3	1 PC	FRT GRILLE WITH CHROME GARNISH CRA -	\$ 898.00
4	1 PC	FRT BUMPER DIS -	\$ 1,710.00
5	1 PC	FRT BUMPER TOW COVER X nn	\$ 56.00
6	3PCS	FRT BUMPER PARKING SENSOR shorted 1pc	\$ 975.00
7	1 PC	FRT BUMPER WASHER JET COVER - RH cut -	\$ 106.00
8	1 PC	FRT BUMPER SIDE RETAINER - RH CRA -	\$ 105.00
9	1 PC	FRT BUMPER LOWER AIR GRILLE nnx	\$ 155.00
10	1 PC	FRT HEADLAMP WASHER JET NOZZLE MOTOR WITH MOTOR - R \$?	215.00
11	1 PC	FRT BUMPER RH LOWER GRILLE mx	\$ 86.00
12	1 PC	FRT BUMP RH LWR GRILLE OUTER CHROME GARNISH ?	\$ 150.00
13	1 PC	FRT BUMPER RH LOWER GRILLE FOG LAMP ?	\$ 595.00
14	1 PC	FRT BUMPER RH GRILLE LOWER CHROME GARNISH mis -	\$ 205.00
15	1 PC	ENGINE UNDERCOVER turn -	\$ 340.00
16	1 PC	FRT RH FENDERSHIELD nnx 3	\$ 220.00
17	1 PC	SUPPORT PANEL ?	\$ 1,098.00
18	1 PC	REAR WINDSCREEN GLASS WITH MOULDING nec -	\$ 1,410.00
19	1 PC	TAILGATE DV -	\$ 2,380.00
20	1 PC	TAILGATE "MERCEDES" EMBLEM nec -	\$ 55.00
21	1 PC	TAILGATE "B200" EMBLEM nec -	\$ 92.00
22	2 1 PC	TAILGATE RED REFLECTOR N/C CRA 1pc	\$ 856.00
23	1 PC	TAILGATE LOCK DV/S	\$ 335.00
24	1 PC	TAILGATE TRIM BOARD (LOWER PART) nnx	\$ 190.00
25	1 PC	REAR BUMPER DS -	\$ 1,770.00
26	1 PC	REAR TAIL LAMP (OUTER) ?	\$ 1,092.00
27	4 1 PC	REAR BUMPER REVERSE SENSOR shorted 2pcs	\$ 1,300.00
28	1 PC	REAR BUMPER LOWER DS -	\$ 210.00
29	1 PC	REAR BUMPER SIDE CHROME GARNISH nec -	\$ 178.00
30	1 PC	REAR BUMPER TOW COVER nnx	\$ 65.00
31	1 PC	REAR BUMPER REINFORCEMENT BT -	\$ 555.00
32	1 PC	REAR BUMPER SIDE RETAINER LH BT -	\$ 24.00
33	1 PC	REAR BUMPER TOP CHROME GARNISH BT -	\$ 300.00
34	1 PC	REAR EXHUAUST MUFFLER BOX BT -	\$ 1,345.00
35	1 PC	REAR EXHUAUST MUFFLER ALUMINIUM COVER BT -	\$ 180.00
36	1 PC	END PANEL ?	\$ 1,365.00
37	1 PC	SPARETYRE PANEL R x	REPAIR \$ -
		BAL C/F	\$ 25,431.00

325.00

428.00

BAL B/F

\$ 25,431.00

LESS 10% \$ (2,543.10)

\$ 22,887.90

38	1 PC	FRT NUMBER PLATE	Xnn	S.NETT	\$ 35.00	
39	1 PC	REAR NUMBER PLATE	BT ✓	S.NETT	\$ 35.00	✓
40	10 PCS	REAR BUMPER CLIPS	hel ✓	S.NETT	\$ 90.00	50
41	1 SET	FRT RH FENDERSHIELD CLIPS	Xnn	S.NETT	\$ 50.00	
42	2 SET	SEALANT	?	S.NETT	\$ 100.00	
43		DIAGNOSE AIRBAG LIGHT - DASHBOARD		FRONT	\$ 150.00	?
43		LABOUR CHARGE		FRONT	\$ 960.00	500
44		SPRAY PAINTING		FRONT	\$ 880.00	600
45		REMOVE AND REFILL AIRCON GAS		FRONT	\$ 160.00	Xnn
46		WIRING		FRONT	\$ 50.00	20
47		TUFF COAT		FRONT	\$ 400.00	60
48		LABOUR CHARGE		REAR	\$ 1,100.00	8w
49		SPRAY PAINTING		REAR	\$ 1,000.00	9w
51		REMOVE AND REFIX RR WINDSCREEN		REAR	\$ 120.00	✓
52		REAR WINDSCREEN SEALANT		REAR	\$ 25.00	✓
53		TUFF COAT		REAR	\$ 80.00	50
54		WIRING		REAR	\$ 50.00	2w
55		LABOUR FOR REVERSE SENSOR		REAR	\$ 80.00	50
					<u>\$ 28,252.90</u>	

Not Authorized

L/S \$ _____

Delays

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: