

ACC. REC'D: Tajm

REF: CC4/LPC.22068308/Tea 3

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD / TP / IS / TP RES / OD RES / EVA / INV / MV
To Inspect/Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No _____
Claims Nil _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SHB6000E Yr Regn: 2021 Dec
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: MG 5 EV Exale T C.C. 120KW
Colour: Green A/C: Insured / Std / NI / NA
Sp. Reading: 9109 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: USJE24056 MG063147
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 205/60R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear
R/Bal.	<u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A.		D.O.I. <u>26/8/22</u>
Survey held at	<u>SMART WL</u>	
Des. of Damages	Frt / Rear / O/S / N/S / U/C / Rooftop or <u>Fr + N/S, 4/c</u>	
The U/C / Chassis frame / Body Structure affected due to collision.		

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?
2) _____

Rep. Format: _____
Lump Sum / I.B.R. / _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS. SI. _____
Photos _____
Others _____
TOTAL _____

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	: 63685592
Estimator Telephone Number	: 68662623
Accident Reporting Number	: 68662672

Date Generated : 26/08/2022

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR FRONT LH PORTION	\$3,000.00	750
total Labour	\$3,000.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$428.00	220
O RESPRAY FRONT HOOD	\$428.00	220
O RESPRAY FRONT FENDER RH	\$428.00	X
O RESPRAY FRONT FENDER LH	\$428.00	220
O RESPRAY FRONT DOOR LH	\$428.00	220
O RESPRAY APRON PANEL LH	\$230.00	?
total Spray Painting & Panel Beating	\$2,370.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	\$112.00	✓
O WASH AND VACUUM	\$60.00	X
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	30
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	40
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	80
O REPLACE SUNDRY PARTS	\$100.00	30
O CHECK & RESET SYSTEM FUNCTION	\$350.00	150
ISOLATED OF (EV) (NET)	\$150.00	✓
O REMOVE AND REFIX UNDERCARRIAGE	\$200.00	150
total Other Costs	\$1,312.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10881944	GEAR SUB ASM-STRG	1.00	\$979.99	10.00	\$881.99	Replace	?
		10437504	ROD ASM-STRG LNKG QTR TIE - LH	1.00	\$129.06	10.00	\$116.15	Replace	?
		10194392	LINK-FRT STAB SHAF	1.00	\$99.53	10.00	\$89.58	Replace	?
		10744820	SHAFT-FRT STAB	1.00	\$218.40	10.00	\$196.56	Replace	?
		10935365	SHAFT ASM-FRT WHL DRV HALF - LH	1.00	\$1,635.80	10.00	\$1,472.22	Replace	?
		10236721- SEPP	HOOD ASM	1.00	\$2,407.29	10.00	\$2,166.56	Replace	bt ✓
		10574081- SEPP	HINGE ASM-HOOD - RH	1.00	\$54.81	10.00	\$49.33	Replace	bt ✓
		10574080- SEPP	HINGE ASM-HOOD - LH	1.00	\$54.81	10.00	\$49.33	Replace	bt ✓
		10321486	WEATHERSTRIP ASM- HOOD RR	1.00	\$20.80	10.00	\$18.72	Replace	X
		K7148511100	BUMPER-HOOD	4.00	\$6.00	10.00	\$21.60	Replace	X
		10328405	HOOD INSULATOR- F/CMPT	1.00	\$70.92	10.00	\$63.83	Replace	X
		10236736- SEPP	FENDER ASM-FRT-RH	1.00	\$379.81	10.00	\$341.83	Replace	Rp
		10236735- SEPP	FENDER ASM-FRT - L	1.00	\$379.81	10.00	\$341.83	Replace	bt ✓
		50004880- SEPP	BRACKET-F/FDR FRT LWR - LH	1.00	\$15.80	10.00	\$14.22	Replace	?
		10533649	INSULATOR ASM-F/FDR -LH	1.00	\$29.22	10.00	\$26.30	Replace	?

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63685592
Estimator Telephone Number	68662623
Accident Reporting Number	68662672

Date Generated : 26/08/2022

User ID : BoonChewTay

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10516114	INSULATOR ASM-F/FDR MID - LH	1.00	\$8.94	10.00	\$8.05	Replace	?
		10169203-SEPP	DOOR ASM-FRT SI - LH	1.00	\$2,338.76	10.00	\$2,104.88	Replace	Rx
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	rec
		10879244	MODULE-FRT END	1.00	\$295.26	10.00	\$265.73	Replace	?
		10894738	BRACKET ASM-HDLP UPP - LH	1.00	\$22.57	10.00	\$20.31	Replace	?
		10894740	BRACKET ASM-HDLP UPP - RH	1.00	\$22.57	10.00	\$20.31	Replace	x
		10892857	LINER ASM-FRT W/H - LH	1.00	\$125.22	10.00	\$112.70	Replace	h
		10325882-SPRP	FASCIA-FRT BPR	1.00	\$721.66	10.00	\$649.49	Replace	cuq
		10361101	GRILLE-FRT BPR FASCIA LOWER	1.00	\$149.03	10.00	\$134.13	Replace	x
		10446164	FINISHER-FRT BPR LOWER - LH	1.00	\$20.38	10.00	\$18.34	Replace	cut
		10361099	COVER-FRT FOG LP - LH	1.00	\$40.25	10.00	\$36.23	Replace	dis
		10361097	FINISHER-FRT FOG LP CVR - LH	1.00	\$47.32	10.00	\$42.59	Replace	dis
		10326366	BRACKET-FRT BPR FASCIA - LH	1.00	\$23.09	10.00	\$20.78	Replace	dis
		10361095	FINISHER-FRT BPR - LH	1.00	\$98.80	10.00	\$88.92	Replace	cut
		10751682	SUPPORT-FRT BPR FASCIA UPR	1.00	\$172.33	10.00	\$155.10	Replace	?
		10954633	PANEL ASM-LEG CTHR	1.00	\$131.04	10.00	\$117.94	Replace	?
		10892798-SEPP	BAR ASM-FRT BPR IMP	1.00	\$624.00	10.00	\$561.60	Replace	?
		10751478	GRILLE ASM-RAD	1.00	\$978.02	10.00	\$880.22	Replace	?
		10737505	COVER-F/CMPT ORNA	1.00	\$217.67	10.00	\$195.90	Replace	?
		10737506	BRACKET-F/CMPT TR PLT	1.00	\$44.51	10.00	\$40.06	Replace	?
		10751567	HEADLAMP ASM - LH	1.00	\$1,098.86	10.00	\$988.97	Replace	cuq
		10806840	STRUT-FRT SUSP - LH	1.00	\$522.29	10.00	\$470.06	Replace	?
		10833026	MOUNT ASM-FRT SUSP STRUT	1.00	\$184.29	10.00	\$165.86	Replace	?
		10580150	ARM ASM-FRT LWR CONT - LH	1.00	\$400.92	10.00	\$360.83	Replace	?
		10124930	KNUCKLE ASM-STRG - LH	1.00	\$252.41	10.00	\$227.17	Replace	?
		10509500	BEARING -S/KNU	1.00	\$452.09	10.00	\$406.88	Replace	?
		10317983	WHEEL	1.00	\$618.07	10.00	\$556.26	Replace	del
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	x
		10313697	HORN ASM-GENERIC (HIGH NOTE)	1.00	\$45.87	10.00	\$41.28	Replace	?
total					\$16,325.01		\$14,727.38		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

06 days
Taufik 974 9574 9/62563561
26/8/22 @ 3:55pm
p/p Resurvey before paint
taufik@lkkauto.com