



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date: 26/8/2022
Vehicle: SNE4130P
Make / Model: TOYOTA PRIUS
INSURANCE AXA

No.	Description	Unit	Unit Price	Amount
1	TAILGATE	1	\$ 1,359.00	\$ X 1,359.00
2	TAILGATE LOGO NN	1	\$ 95.50	\$ X 95.50
3	TAILGATE EMBLEM PRIUS t NN	1	\$ 89.40	\$ X 89.40
4	TAILGATE EMBLEM HYBRID NN	1	\$ 82.30	\$ X 82.30
5	TAILGATE DETECTOR NN	1	\$ 321.00	\$ X 321.00
6	REAR BUMPER NN	1	\$ 658.00	\$ del 658.00
7	REAR BUMPER SIDE RETAINER LH X NN	1	\$ 112.00	\$? 112.00
8	REAR BUMPER REINFORCEMENT X NN	1	\$ 350.50	\$? 350.50
9	REAR BUMPER LIP	1	\$ 728.90	\$ del 728.90
10	REAR BUMPER REFLECTOR LH NN	1	\$ 68.00	\$ X 68.00
11	REAR END PANEL	1	\$ 612.00	\$ R 612.00
12	REAR END PANEL TOP GARNISH NN	1	\$ 212.00	\$ X 212.00
			25	\$ 4,688.60
			Less 20%	\$ 937.72
			Total	\$ 3,750.88
	S/Nett items:			
1	REAR BUMPER CLIPS	1	\$ 80.00	\$ 30 80.00
2	REAR REVERSE SENSOR	1	\$ 250.00	\$ nw/ 250.00
3	REAR END PANEL TOP GARNISH CLIPS NN	1	\$ 80.00	\$ X 80.00
4	REAR END PANEL SEALANT NN	1	\$ 60.00	\$ X 60.00
				\$ 470.00
	Labour to: REAR			
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 150.00	\$ X 150.00
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 30 150.00
3	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 200.00	\$ 60 200.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	\$ X 100.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 250 600.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 250 600.00
				\$ 1,800.00
Taufik 92495749 WP 26/8/22 @ 11am Resurvey After Repair 2 days taufik@lkkauto.com			Parts Replacement Amount	\$ 4,220.88
			Total Amount for Labour	\$ 1,800.00
			Total Amount	\$ 6,020.88

549 ✓

✓

1277.90
-25%
958.42

230

590

1778.42

L/S - 1422.73
= 1400

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: