

ASS. REC. BY:

REF:

AIG / 22008310 / Kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

31/8 21 Lm @ 7501

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS. St

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

N/S	O/S

Veh No:

SMH 7091U

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

c.c

1496

Colour

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

254055

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP5

1338962

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Triangle

195/50R15

R: Fixa78

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

8

mm

L/Bal.

5

mm

L/Bal.

8

mm

D.O.A.

27/7/22

D.O.I.

26/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date: 26/08/2022

Vehicle No: SMH7091U

Model: HONDA FIT HYBRID 1.5

Chassis: GP51336962-2018

Reg.Year: 2019

Third Party Insurer: AIG

Third Party Veh No: SJB9001J

Date of Accident: 27/07/2022

Estimator: TING AN

Surveyor:

*Not Authorised
11/10/2022*

*Running After Pain
2 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>11</i> \$947.40
2	REAR TAILGATE "FIT" EMBLEM	1		<i>nn</i> \$42.90
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>nn</i> \$58.50
4	REAR TAILGATE WEATHERSTRIP	1		<i>1m</i> \$102.30
5	REAR WINDSCREEN MOULDING	1		<i>nn</i> \$110.80
6	REAR BUMPER	1		<i>Bu</i> \$568.30
7	REAR BUMPER SIDE BRACKET RH	1		<i>1m</i> \$28.80
8	REAR BUMPER REFLECTOR RH	1		<i>1m</i> \$40.90
9	REAR BUMPER LOWER GARNISH COVER RH	1		<i>1m</i> \$86.80
10	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,986.70
LESS 20%				-\$397.34
PARTS TOTAL				\$1,589.36

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>nn</i> \$80.00
2	REAR BUMPER CLIPS	1		<i>nn</i> \$50.00
3	REAR BUMPER REVERSE SENSOR	1		<i>1m</i> \$300.00
S/N TOTAL				\$430.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00 *2000*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$700.00 *2000*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

nn \$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

nn \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *500*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26/08/2022
Vehicle No: SMH7091U
Model: HONDA FIT HYBRID 1.5
Chassis: GP51336962-2018
Reg. Year: 2019

Third Party Insurer: AIG
Third Party Veh No: S1880001
Date of Accident: 27/07/2022
Estimator: TING AN
Surveyor:

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

TO CHECK WIRING & ELECTRICAL SYSTEM.

na \$100.00 *X*

na \$80.00 *X*

LABOUR TOTAL \$1,970.00

TING AN TOTAL \$3,989.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: