

Think One Autocare Pte Ltd
No: 6 Jalan Lam Huat #02-32 Carros Centre
Singapore 737869

GBF9864J TOYOTA HIACE

DATE 25.08.2022

No	Qty	PARTICULAR	AMOUNT S\$
1	1	TAIL GATE	1855 2,062.00 <i>bt</i>
2	1	TAIL GATE LOCK	509.20 <i>mm</i>
3	1	TAIL GATE LOCK COVER	98.00 <i>x ny</i>
4	1	TAIL GATE (LOGO) EMBLEM	79 165.00 <i>de</i>
5	2	TAIL GATE RUBBER STOPPER	20.00 40.00 <i>x ny</i>
6	1	REAR END PANEL INNER	1,288.00 <i>de</i>
7	1	REAR END PANEL OUTER	1,288.00 <i>de</i>
8	1	REAR BUMPER	681.20 1,260.00 <i>de</i>
9	2	REAR BUMPER SIDE RETAINER R+L	121.50 243.00 <i>x ny</i>
10	1	TAIL LAMP LOWER COVER LH	185.00 <i>de</i>
11	1	TAIL LAMP LH	764.50 <i>x ny</i>
			<u>\$ 7,902.70</u>
			<i>25% - 2100.15 LESS 25%</i>
			<u>\$ 1,975.67</u>
			<u>\$ 5,927.02</u>

No	Qty	PARTICULAR	SPECIAL NETT	AMOUNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT		60 90.00 <i>de</i>
2	1	REAR WINDSCREEN GLASS INNER SEAL		135.00 <i>de</i>
3	1	70 KM/H STICKER		25.00 <i>de</i>
4	1	REVERSE SENSOR		250.00 <i>200mm</i>
5	1	COMPANY NAME & LOGO		720 850.00 <i>300mm</i>
				<u>\$ 1,350.00</u>

LABOUR & MISCELLANEOUS:

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,400.00 <i>600</i>
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	600 1,000.00
3	To transfer tail gate components with all necessary attachments	60 150.00
4	To remove, refix rear windscreen glass and water test	120 150.00
5	To install reverse sensor and test function	30 100.00
		<u>\$ 2,800.00</u>

Tanfik 97495749
Wt' 26/8/20 @ 1140
L/S Resurvey after repair
Tanfik @ 11hant@com
04 days

1410
2100.15
720
1410
4230.15
L/S \$3400, 4 days
#