

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 12 days Res.: Yes or No
Lum Sum: 71P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 4648P Yr Regn: Dec / 2019
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai Ioniq c.c. 1580
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 322915 T/Radio: Insured / Std / NI / NA
Eng/No: G4LEKU400509
C/No: KMTHC851CVLU187511
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65 R15
R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 26/08/2022 D.O.I. 29/08/2022
Survey held at B. Park Sin Ming
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Portion
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Chine Taping GSD 5048K 5048K
14/2/2023	issued P/P 17,294.12 with 12 days of eq

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Aug-22

INSURANCE: China Taiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 4648 P

Description	Qty	List Price	Amount
Frt Door(LH) <i>out Denhi</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>src</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH) <i>HN</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH <i>HN</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH) <i>HN</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH) <i>HN</i>	1	\$ 153.70	\$ 153.70
Front Door Check (LH) <i>HN</i>	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (LH) <i>HN</i>	1	\$ 385.60	\$ 385.60
Front Door Outer Handle (LH) <i>Denhi</i>	1	\$ 234.80	\$ 234.80
Front Door Mirror ASSY (LH) <i>Denhi</i>	1	\$ 1,691.70	\$ 1,691.70
Front Door Protector(LH) <i>HN</i>	1	\$ 186.20	\$ 186.20
Front Door Outer Moulding (LH) <i>src</i>	1	\$ 110.10	\$ 110.10
Rear Door (LH) <i>Denhi</i>	1	\$ 2,147.90	\$ 2,147.90
Rear Door Rubber(LH) <i>src</i>	1	\$ 280.00	\$ 280.00
Rear Door Outer Moulding(LH) <i>src</i>	1	\$ 125.30	\$ 125.30
Rear Door Outer Handle (LH) <i>HN</i>	1	\$ 124.80	\$ 124.80
Rear Door Channel (LH) <i>HN</i>	1	\$ 358.30	\$ 358.30
Rear Door Gear/Regulator(LH) <i>HN</i>	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH) <i>HN</i>	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy <i>HN</i>	1	\$ 306.40	\$ 306.40
Rear Door Hinge Upper (LH) <i>HN</i>	1	\$ 173.88	\$ 173.88
Rear Door Hinge Lower (LH) <i>HN</i>	1	\$ 170.50	\$ 170.50
Rear Door Check(LH) <i>HN</i>	1	\$ 85.92	\$ 85.92
Rear Door Protector(LH) <i>HN</i>	1	\$ 166.20	\$ 166.20
Boot Lid <i>HN</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>src HN</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>HN</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HN</i>	2	\$ 86.70	\$ 173.40
Boot Lid 'H' Emblem <i>HN</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HN</i>	1	\$ 24.30	\$ 24.30
Emblem-Ionic <i>HN</i>	1	\$ 31.30	\$ 31.30
Boot Lid Lamp(LH) <i>HN</i>	1	\$ 822.00	\$ 822.00
Boot Lid Glass Upper Moulding <i>HN</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HN</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>HN</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>HN</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH) <i>HN</i>	1	\$ 188.10	\$ 188.10
Rear Bumper Centre Moulding Assy <i>HN</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>HN</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HN</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH) <i>HN</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>HN</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Side Under(LH) <i>HN</i>	1	\$ 123.10	\$ 123.10

Rear Bumper Reflector Lamp(LH) <i>SN</i>	1	\$ 82.90	\$ 82.90
Tail Lamp(LH) <i>broken</i>	1	\$ 935.40	\$ 935.40
Tail Lamp Quarter Panel(LH) <i>HH</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>HH</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
Rear Fender(LH) <i>Damage</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (LH) <i>HH</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (LH) <i>HH</i>	1	\$ 165.50	\$ 165.50
Rear Fender Air-Duct (LH) <i>SN</i>	1	\$ 87.30	\$ 87.30
Rear Fender Trim Board (LH) <i>HH</i>	1	\$ 788.75	\$ 788.75
Assy BSD Blind Spot Radar (LH) <i>bracket at</i>	1	\$ 1,784.40	\$ 1,784.40
Rear Tyre Rim (LH) <i>HH</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (LH) <i>HH</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>HH</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(LH) <i>HH</i>	1	\$ 265.40	\$ 265.40
Rear Assist (LH) <i>HH</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(LH) <i>HH</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (LH) <i>HH</i>	1	\$ 175.60	\$ 175.60
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(LH) <i>HH</i>	1	\$ 239.50	\$ 239.50
Rear Lower Arm(LH) <i>HH</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (LH) <i>HH</i>	1	\$ 538.10	\$ 538.10
SUB TOTAL			\$ 29,133.08
LESS 20%			\$ 5,826.62
DISCOUNTED TOTAL			\$ 23,306.46
Front Door Comfort Logo (LH) <i>HCC</i>	SN	1	\$ 75.00
Rear Door Comfortdelgro & Apps Sticker(LH) <i>HCC</i>	SN	1	\$ 80.00
Boot Lid Comfort Logo & Tel No. Sticker <i>HCC</i>	SN	1	\$ 35.00
Rear Windscreen Sealant <i>HH</i>	SN	2	\$ 46.00
Rear Tyre(LH) <i>HH</i>	SN	1	\$ 216.00
SUB TOTAL			\$ 498.00
Labour Charge			
Panel Beating	1	\$2,200.00	\$2,200.00
Spray Painting Charge	1	\$2,000.00	\$2,000.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00
Re-set Rear Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00

14,865.25

11,892.20

190.00

800/-

900/-

30/-

40/-

HH

80/-

80/-

HH

HH

60/-

HH

60/-

HH

Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	\$550.00
TOTAL LABOUR			\$7,130.00
ESTIMATE TOTAL			\$30,934.46

150/-
2200/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

09/08/2022 @ 0945hrs

Not Answered
P/P
2/5/22

12 days
Jym

LKK Auto

8

14,282.20

Supp 3,011.92

P/P 17,294.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIFROST AUTO PTE LTD

SUPPLEMENTARY

DATE: 29-Aug-22

INSURANCE: China Topy

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 4648 P (S)

Description	Qty	List Price	Amount
Door Centre Pillar Outer (LH) <i>2nd</i>	1	\$ 3,764.90	\$ 3,764.90
SUB TOTAL			\$ 3,764.90
LESS 20%			\$ 752.98
DISCOUNTED TOTAL			\$ 3,011.92
ESTIMATE TOTAL			\$3,011.92

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrotauto.com

1 gm

24K Auto

8