

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.08.2022

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SML6151R**
MODEL : **TOYOTA CAMRY HYBRID**
DATE OF ACCIDENT : 17.08.2022
TIME OF ACCIDENT : 09:55HRS

AXVH 701023344

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Reh d</i>	1	\$ 625.70	\$ 625.70
2	REAR BUMPER DIFFUSER <i>Reh d</i>	1	\$ 393.50	\$ 393.50
3	REAR BUMPER REFLECTOR <i>Reh</i>	2	\$ 125.60	\$ 251.20
4	REAR BUMPER SIDE RETAINER (SIDE) <i>Reh</i>	2	\$ 128.30	\$ 256.60
5	REAR BUMPER REINFORCEMENT <i>Reh d</i>	1	\$ 319.70	\$ 319.70
6	REAR BUMPER REINFORCEMENT BRACKET <i>Reh</i>	2	\$ 171.20	\$ 342.40
7	TAILLAMP <i>Reh</i>	2	\$ 890.20	\$ 1,780.40
8	TAILLAMP SIDE GARNISH <i>Reh</i>	2	\$ 30.10	\$ 60.20
9	TAILLAMP LOWER BRACKET <i>Reh</i>	2	\$ 59.60	\$ 119.20
10	REAR FENDER INNER COWLING <i>Reh</i>	2	\$ 218.60	\$ 437.20
11	REAR FENDER INNER TRIM <i>Reh</i>	2	\$ 790.90	\$ 1,581.80
12	BOOTLID <i>Buckled</i>	1	\$ 1,143.70	\$ 1,143.70
13	BOOTLID LAMP <i>Reh</i>	2	\$ 615.50	\$ 1,231.00
14	BOOTLID LOGO <i>Reh</i>	1	\$ 49.80	\$ 49.80
15	BOOTLID EMBLEM 'HYBRID' <i>Reh</i>	1	\$ 59.80	\$ 59.80
16	BOOTLID HINGE <i>Reh</i>	2	\$ 228.20	\$ 456.40
17	BOOTLID STOPPER <i>Reh</i>	2	\$ 24.80	\$ 49.60
18	BOOTLID INSULATOR <i>Reh</i>	1	\$ 549.50	\$ 549.50
19	BOOTLID LOCK <i>Damaged</i>	1	\$ 339.80	\$ 339.80
20	BOOTLID CATCHER <i>Reh</i>	1	\$ 39.41	\$ 39.41
21	BOOTLID WEATHERSTRIP <i>ht</i>	1	\$ 256.40	\$ 256.40
22	BOOTLID DETECTOR <i>Damaged</i>	1	\$ 194.50	\$ 194.50
23	BOOTLID DETECTOR WIRE HARNESS <i>Reh</i>	1	\$ 469.60	\$ 469.60
24	REAR END PANEL <i>Dented</i>	1	\$ 651.70	\$ 651.70

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SML6151R**
 MODEL : **TOYOTA CAMRY HYBRID**
 DATE OF ACCIDENT : 17.08.2022
 TIME OF ACCIDENT : 09:55HRS

25	REAR END PANEL TOP GARNISH <i>Rehd</i>	1	\$ 296.20	\$ 296.20	✓
26	REAR FLOOR PANEL TOP BOARD <i>Rehd</i>	1	\$ 517.20	\$ <u>517.20</u>	486
27	REAR FLOOR PANEL BOTTOM GARNISH <i>Rehd</i>	1	\$ 496.80	\$ 496.80	+
28	REAR FLOOR TOP SPONGE (CENTER) <i>Rehd</i>	1	\$ 498.70	\$ <u>498.70</u>	✓

5567-10
A17532

TOTAL PRICE \$ 13,468.01
 LESS 25% \$ 3,367.00
SUB TOTAL PRICE \$ 10,101.01

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Rehd</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00
3	BOOTLID INSULATOR CLIP (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00
4	TAILLAMP CLIPS (SET) <i>Rehd</i>	1	\$ 30.00	\$ 30.00
5	REAR FENDER COWLING CLIPS (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00
7	BOOTLID SEALANT <i>Rehd</i>	1	\$ 150.00	\$ 150.00
8	BOOTLID INSULATOR CLIP (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00
9	REAR END PANEL INSULATION SEAL <i>Rehd</i>	1	\$ 80.00	\$ 80.00
10	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>Rehd</i>	1	\$ 80.00	\$ 80.00

90

TOTAL \$ 790.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>80</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>80</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SML6151R**
MODEL : **TOYOTA CAMRY HYBRID**
DATE OF ACCIDENT : 17.08.2022
TIME OF ACCIDENT : 09:55HRS

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$4,250.00

TOTAL PARTS COST : \$ 10,891.01
TOTAL LABOUR COST : \$ 4,250.00
TOTAL REPAIR COST : \$ 15,141.01

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
L/S 30/08/22
06/09/22

total: 6175.32
L/S: ASK

1910