



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Ref: CS/INC22008323/Rcy3 Date: 29/08/2022  Code: INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBH 8926K	Veh. Inspected	SBS 5023C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1185998-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	29/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	23/08/2022	Inspection Date	29/08/2022
Survey held at	15 ANG MO KIO ST 63 SINGAPORE 569117		
Repairer	SBS TRANSIT LTD (HQ)		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			