

MBM WHEELPOWER PTE. LTD.

JUR REF.: SLA887K


UR REF.: SDS8900C

D: NTUC INCOME

D: MOTOR CLAIMS DEPARTMENT

AX:

ESTIMATE FOR VEHICLE NO.: SDS8900C



DATE: 29/8/2022
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA COROLLA 1.6
CHASSIS NO.: MR053ZEC107118760
ENGINE NO.: 3ZZ4562939
YEAR MADE: 2006
ACCIDENT DATE: 24 August 2022

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
	FRONT FENDER RH		1	\$ 1,200.00
	FRONT FENDER LAMP RH		1	\$ 55.00
	FRONT FENDER INNER SHIELD RH		1	\$ 150.00
	FRONT FENDER INNER SHIELD CLIP		10	\$ 50.00
	SIDE MIRROR OUTER REAR VIEW MIRROR RH		1	\$ 390.00
	SIDE MIRROR COVER RH		1	\$ 60.00
	FRONT DOOR WINDOW GLASS RUN RH		1	\$ 200.00
	FRONT DOOR RH		1	\$ 850.00
	FRONT DOOR WEATHERSTRIP RH		1	\$ 150.00
	FRONT DOOR REAR LOWER FRAME RH		1	\$ 200.00
	FRONT DOOR UPPER HINGE RH		1	\$ 75.00
	FRONT DOOR LOWER HINGE RH		1	\$ 75.00
	FRONT DOOR LOCK RH		1	\$ 250.00
	FRONT DOOR CHECK RH		1	\$ 130.00
	FRONT DOOR LOWER FRAME BRACKET RH		1	\$ 50.00
	FRONT DOOR BOARD RH		1	\$ 900.00
	FRONT DOOR TAPE RH		1	\$ 80.00
	FRONT DOOR INSIDE HANDLE RH		1	\$ 350.00
	FRONT DOOR OUTSIDE HANDLE FRAME RH		1	\$ 200.00
	FRONT DOOR OUTSIDE HANDLE RH		1	\$ 300.00
	FRONT DOOR WINDOW REGULATOR RH		1	\$ 110.00
	FRONT DOOR POWER WINDOW REGULATOR RH		1	\$ 800.00
	REAR DOOR WINDOW GLASS RUN RH		1	\$ 200.00
	REAR DOOR QUARTER GLASS WEATHERSTRIP RH		1	\$ 250.00
	REAR DOOR WINDOW BAR DIVISION RH		1	\$ 200.00
	REAR DOOR RH		1	\$ 850.00
	REAR DOOR WEATHERSTRIP RH		1	\$ 150.00

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

REAR DOOR BOARD RH
 REAR DOOR TAPE RH
 REAR DOOR CHECK RH
 REAR DOOR UPPER HINGE RH
 REAR DOOR LOWER HINGE RH
 REAR DOOR LOCK RH
 REAR DOOR WINDOW REGULATOR RH
 REAR DOOR POWER WINDOW REGULATOR RH
 FRONT TYRE RIM RH

1	\$	Sn	900.00	X
1	\$	na	70.00	X
1	\$	Sn	130.00	X
1	\$	7	75.00	X
1	\$	11	75.00	X
1	\$	11	250.00	X
1	\$	Sn	110.00	X
1	\$	Sn	800.00	X
1	\$	Ref	350.00	✓

TOTAL: \$ 11,035.00
 LESS 30%: \$ (3,310.50)
 PARTS TOTAL: \$ 7,724.50

SPECIAL NETT

NUMBER PLATE & HOLDER
 BODY SEALANT

1	\$	Sn	50.00	X
1	\$	na	50.00	X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
 TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS
 TO CHECK & RECONNECT ALL NECESSARY WIRING
 TO REMOVE & REFIT ALL SENSOR
 TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
 TO SPRAY PAINT ON THE AFFECTED AREAS

\$	800/	1,800.00
\$	80/	200.00
\$	20/	200.00
\$	na	250.00 X
\$	na	250.00 X
\$	800/	1,600.00

TOTAL: \$ 12,124.50
 7% GST: \$ 848.72
 GRAND TOTAL: \$ 12,973.22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MBM WHEELPOWER PTE. LTD.

UR REF.: SLA887K
R REF.: SDS8900C

NTUC INCOME
MOTOR CLAIMS DEPARTMENT



DATE: 30/8/2022
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA COROLLA 1.6
CHASSIS NO.: MR053ZEC107118760
ENGINE NO.: 3ZZ4562939
YEAR MADE: 2006
ACCIDENT DATE: 24 August 2022

PPLEMENTARY FOR VEHICLE NO.: SDS8900C

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	HEADLAMP RH <i>331-40</i>		1	\$ 600.00 ✓
2	FRONT BUMPER SIDE RETAINER RH		1	\$ 50.00 ✓
3	FRONT FENDER SIDE PANEL PROTECTOR RH		1	\$ 50.00 ✓
4	FRONT WHEEL HUB RH		1	\$ 200.00 ✓
5	FRONT WHEEL BEARING RH		1	\$ 100.00 ✓
6	FRONT ABSORBER RH		1	\$ 120.00 ✓
7	FRONT STABILISER LINK		1	\$ 150.00 X
8	FRONT KNUCKLE ARM RH		1	\$ 400.00 ✓
9	FRONT LOWER BALL JOINT		1	\$ 200.00 X
10	FRONT LOWER ARM RH		1	\$ 400.00 X
TOTAL: \$				2,270.00
LESS 30% <i>508</i>				(681.00)
PARTS TOTAL: \$				1,589.00

LABOUR

TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$ 80.00 <i>601</i>
TO REMOVE & REFIT FRONT TYRE RIM	\$ 50.00 <i>201</i>
TO REMOVE & REFIT LH FRONT & REAR DOOR GLASS	\$ 200.00 <i>601</i>
TOTAL: \$	1,919.00
7% GST: \$	134.33
GRAND TOTAL: \$	2,053.33

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 6888 f 6452 5333
COMPANY REG. NO.: 200204110W