

TP 111
Asher.

SLP 5819X. 2017 June.
Mazda 3 HB. 1496 CC
JM6BN24A8H01S68GT.

Distorted

Rear Bumper

1124.50 ✓
~~50(SN)~~ 30(SN)

Rear Bumper Clips. ^{MR}

Rear Bumper Side Holder x 02. ^{RH} RD

64.30 ✓
 $64.3 \times 2 = 128.60$

Rear Bumper Reflector RH. ^{MR}

58.80 ✓

Rear Bumper Reinforcement. ^{Dented}

564.20 ✓

Rear Bumper Tow Cover ^{Dented}

43.50 ✓

Rear Bumper Sensor x 04 ^{2 pieces} ^{dented}

$319 \times 4 = 1276$ 638

Rear Bumper Sensor Holder x 04. ^{MR}

$20 \times 4 = 80$ ✓

Rear End Panel ^{Dented}

676.30 ✓

Rear End Panel Top Garnish. ^{Dented} ^{MR}

105.10 ✓

Rear End Panel Top Garnish Clips. ^{MR}

20(SN) ✓

Rear End Panel Sealant. ^{MR}

60(SN) ✓

Tail Lamp RH. ^{MR}

926. ✓

Tail Lamp Panel RH. ^{Buckled}

489.10 ✓

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLP5819X.

Tailgate	Dented	1332.20. ✓
Tailgate Lock	and	321.20. ✓
Tailgate Weatherstripe	lt	368.20. ✓
Tailgate Outer Garnish	and	427.90. ✓
Tailgate Outer Garnish Clips	per	30(SN). ✓
Tailgate Reflector RH.	new	586.50. ✗
Tailgate Lower Trim Board	and	585.40. ✓
Tailgate Lower Trim Board Clips	per	30(SN). ✓
Tailgate Glass Moulding	per	165.20. ✓
Tailgate Glass Sealant		60(SN). ✓
Mazda Logo	per	75.60. ✓
Mazda Bolding.		68.90. ✓
SKYActiv Emblem.		69.90. ✓
Rear RH Fender	Repair	1284.20. ✗

SLP 5819X.

Rear RH Fender Inner Trim Board ^{measured} 485.20 ✓
 Rear RH Fender Inner Trim Board Clips ^m 30(SN) ✓
 Spare Tyre Panel Top Board. 2 308.60 ✓
 Rear Exhaust Pipe. 1HP 1075.80. ✓
 Rear Exhaust Pipe Mounting. 1HP 35.90. ✓
 8669.50 S.N: 260
 6938.60

Panel Beating	1500	1200
Spray Painting.	1400	1100
Wiring.	100	30
To spray buff coat.	150	80
To remove upholstery.	130	80
To remove reverse sensor	100	60
To remove rear camera.	100	50
To remove video recorder.	100	50
To transfer tailgate fittings.	150	80
To remove tailgate glass	180	120
To remove exhaust pipe.	150. X	
		total: 10065.60
		L/S: 8K.
		07 Days.