

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : ERGO Insurance Pte Ltd

-

ATTN: Motor Claim Department

Your Ref No: BOON POH REFUSE

Claim Type: Own Damage

Accident Date: 23/08/2022

Estimate No: ES1700991

Date: 23 Aug 2022

Policy No: DMPCG22003084

Veh Reg No: **YP1782P**

Make/Model: ISUZU NPR85UH5A

Chassis No: JAANPR85HG7100144

Engine No: 4JJ12J3793

Reg. Date: 24/03/2016

Estimate Repair Cost to Vehicle No :YP1782P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Front Bumper	1,179.80	1 PC	1,179.80	
2 Front Bumper Bracket RH	154.40	1 PC	154.40	
3 Front Corner Panel RH	317.50	1 PC	317.50	
4 Front Corner Panel Top Black Cover RH	98.58	1 PC	98.58	
5 Front Corner Panel Rubber RH	128.60	1 PC	128.60	
6 Front Panel	1,081.30	1 PC	1,081.30	
7 Front Inner Panel Reinforcement	729.30	1 PC	729.30	
8 Front Panel Rubber Seal	213.88	1 PC	213.88	
9 Front Wiper Panel	1,058.88	1 PC	1,058.88	
10 Front Grille	508.20	1 PC	508.20	
11 Front Windscreen	1,078.00	1 PC	1,078.00	
12 Front Windscreen Molding	567.88	1 PC	567.88	
13 Front Windscreen Molding Lower	368.88	1 PC	368.88	
14 Wiper Blade	87.88	2 PC	175.76	
15 Wiper Arm Assy	145.88	2 PC	291.76	
16 Wiper Link Assy	129.80	1 PC	129.80	
17 Wiper Tank	967.38	1 PC	967.38	
18 Wiper Motor Assy	578.58	1 PC	578.58	
19 Headlamp Assy RH	279.40	1 PC	279.40	
20 Headlamp Bracket RH	112.20	1 PC	112.20	
21 Signal Lamp Assy RH	104.50	1 PC	104.50	
22 Headlamp Lower Garnish RH	689.58	1 PC	689.58	
23 Side Mirror Stay RH	349.80	1 PC	349.80	
24 Side Mirror Arm RH	488.58	1 PC	488.58	
25 Side Mirror Arm Round Cover RH	37.10	1 PC	37.10	
26 Side Mirror RH	140.80	1 PC	140.80	
27 Front Door Assy RH	3,683.40	1 PC	3,683.40	
28 Front Door Frame RH	1,673.40	1 PC	1,673.40	
29 Front Door Lamp RH	550.80	1 PC	550.80	
30 Front Door Pillar RH	930.90	1 PC	930.90	
31 Front Door Hinge Top RH	107.30	1 PC	107.30	
32 Front Door Hinge Lower RH	121.60	1 PC	121.60	
33 Front Door Stopper RH	47.20	1 PC	47.20	
34 Front Door Glass RH	490.60	1 PC	490.60	
35 Front Door Regulator RH	811.00	1 PC	811.00	
36 Front Door Regulator Motor RH	668.10	1 PC	668.10	
37 Front Door Trim Outer RH	665.00	1 PC	665.00	
38 Front Door Trim Inner RH	522.00	1 PC	522.00	
39 Front Door Board RH	726.40	1 PC	726.40	

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : ERGO Insurance Pte Ltd

-

ATTN: Motor Claim Department

Your Ref No: BOON POH REFUSE

Claim Type: Own Damage

Accident Date: 23/08/2022

Estimate No: ES1700991

Date: 23 Aug 2022

Policy No: DMPCG22003084

Veh Reg No: YP1782P

Make/Model: ISUZU NPR85UH5A

Chassis No: JAANPR85HG7100144

Engine No: 4JJ12J3793

Reg. Date: 24/03/2016

Estimate Repair Cost to Vehicle No :YP1782P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
40 Front Door Lock Assy RH	173.00	1 PC	173.00	
41 Front Door Bottom Garnish RH	267.40	1 PC	267.40	
42 Front Door Seal RH	220.20	1 PC	220.20	
43 Power Window On/Off Switch RH	247.50	1 PC	247.50	
44 Cabin Roof Panel	4,073.00	1 PC	4,073.00	
45 Front Fender Scuff Plate RH	531.88	1 PC	531.88	
46 Front Step Garnish RH	225.90	1 PC	225.90	
47 Front Muguard Rubber RH	128.85	1 PC	128.85	
48 Front Mudguard RH	328.88	1 PC	328.88	
49 Front Mudguard Plate RH	130.15	1 PC	130.15	
50 Front Mudguard Rubber Cover Seal RH	78.88	1 PC	78.88	
51 Front Mudguard Inner Seal RH	288.88	1 PC	288.88	
52 Front Fender RH	546.88	1 PC	546.88	
53 Front Fender Protector RH	128.88	1 PC	128.88	
54 Dashboash Assy	2,181.30	1 PC	2,181.30	
55 Dashboash Reinforcement	1,083.50	1 PC	1,083.50	
56 Dashboard Meter Panel	858.88	1 PC	858.88	
57 Meter Assy	935.00	1 PC	935.00	
58 Brake Reservoir Tank	387.55	1 PC	387.55	
59 Brake Panel Bracket	1,200.68	1 PC	1,200.68	
60 Brake Pedel	968.86	1 PC	968.86	
61 Brake Master Pump	678.88	1 PC	678.88	
62 Aircond Heater Unit Assy	2,088.58	1 PC	2,088.58	
63 Aircond Compressor Assy	1,518.00	1 PC	1,518.00	
64 Aircond Blower Assy	1,128.88	1 PC	1,128.88	
65 Aircond Blower Motor	858.78	1 PC	858.78	
66 Aircond Condensor Assy	1,068.78	1 PC	1,068.78	
67 Aircond Condensor Fan	458.88	1 PC	458.88	
68 Aircond Condensor Fan Motor	856.99	1 PC	856.99	
69 Aircond Discharge Hose	118.80	1 PC	118.80	
70 Aircond Suction Hose	41.80	1 PC	41.80	
71 Aircond Cooling Coil	690.00	1 PC	690.00	
72 Air Dust Assy	1,866.78	1 PC	1,866.78	
73 Air Dust Intake	867.55	1 PC	867.55	
74 Drag Link Assy	1,809.58	1 PC	1,809.58	
			51,866.47	
		Less 10%	5,186.65	46,679.78
Net Price				
75 Brake Fluid	10.00	1 BTL	10.00	

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : ERGO Insurance Pte Ltd

-

ATTN: Motor Claim Department
 Your Ref No: BOON POH REFUSE
 Claim Type: Own Damage
 Accident Date: 23/08/2022

Estimate No: ES1700991
Date: 23 Aug 2022
Policy No: DMPCG22003084
Veh Reg No: YP1782P
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HG7100144
Engine No: 4JJ12J3793
Reg. Date: 24/03/2016

Estimate Repair Cost to Vehicle No :YP1782P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			10.00	10.00
Labour				
76 Labour to renew all lamps & connect wire .	580.00	1 JOB	580.00	
77 Labour to refocus headlamp .	150.00	1 JOB	150.00	
78 Labour to dismantle & refit windscreen .	280.00	1 JOB	280.00	
79 Labour to do wheel realignment .	280.00	1 JOB	280.00	
80 Labour to dismantle door assy & refit & renew all parts .	380.00	1 JOB	380.00	
81 Labour to renew all aircons parts & top up aircon gas .	850.00	1 JOB	850.00	
82 Labour to knock & renew all affected area .	3,500.00	1 JOB	3,500.00	
83 To spray & painting on all affected area .	2,800.00	1 JOB	2,800.00	
			<u>8,820.00</u>	<u>8,820.00</u>
			Total	S\$ 55,509.78
			Add GST @ 7%	<u>3,885.68</u>
			Total Amount Payable	<u>S\$ 59,395.46</u>

TOTAL: SINGAPORE DOLLAR FIFTY NINE THOUSAND THREE HUNDRED NINETY FIVE AND CENTS FORTY SIX ONLY

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

 AUTHORISED SIGNATURE