



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22008354/Uny3q2 Date: 19/09/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2692J	Veh. Inspected	YQ 4771X	
Policy No.	D22MTPCVE002071	Coverage (\$)	0.00	
Claim No.	CMTD2202988/LOR	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	29/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R (M)	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JHHUCV3F50K041277	Colour	WHITE	
Odometer	27344 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	195/85 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	5/5 mm	
L/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2022	Inspection Date	29/08/2022	
Survey held at	39 Woodlands Close, MEGA@Woodlands #01-24			
Repairer	NINETEEN AUTOWERKS PTE. LTD.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	