

NINETEEN AUTOWERKS PTE LTD
436 TAMPINESS STREET 43 #07-97
SINGAPORE 520436
 HP: 96741991(Vessie Foo)

Not Authorized
 29/08/22
 4/5 @ 1800/
 4 days

Estimate for YQ4771X(Hino ZXU710R)

1 *REAR RH TAILLAMP

260

1310 \$498.30
 \$498.30
 \$74.75
 \$423.56

Less 15%

S/Nett

1 *REAR BUMPER REINFORCEMENT

1 *REAR END PANEL *wooden lower*

1 *REAR FLOOR END PANEL

1 *REAR RH TAILLAMP BRACKET

1 *REAR RH TAILLAMP BRACKET BULT & NUT

1 *REAR STEP WOOD PANEL

1 *REAR TAILGATE 23PAX STICKER

1 *REAR TAILGATE 60KM STICKER

1 *REAR TAILGATE FRAME

4 *REAR TAILGATE HINGES RH

4 *REAR TAILGATE HINGES RH BULT & NUT - SET

R \$1,000.00 X
 one \$800.00 ✓
 R \$680.00 X
 3nt \$140.00 ✓
 11 \$40.00 X
 2u \$480.00 X
 nu \$25.00 10
 11 \$25.00 10
 R \$1,580.00 X
 11 \$880.00 X
 11 \$400.00 X
 \$6,050.00

TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK
 LIGHTING, AND REWIRE FOR PARKING SENSOR

\$120.00 20

TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR
 PORTION, AND WHERE CONSISTENT TO THE ACCIDENT

\$1,000.00 500

TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE
 DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN
 BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT
 TO THE ACCIDENT

\$1,000.00 500

TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL

11 \$120.00 X

\$2,240.00

Total

\$8,713.56

P-260
 153

P-21
 S.N-960

L-1100

2281

20%

1824

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s), during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: