

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0742/2022/EQ
DATE : 29-Aug-22
WIP : 39449

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/9/2022.

YOUR INSURED VEH NO : SLU 312 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MDM. GUO CHENG @GUO CHEN
ADDRESS : 199B PUNGGOL FIELD
#12-413
SINGAPORE 822199
TELEPHONE : HP +65 96867796
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5114411081-02
VEHICLE NO : **SKE 2296 T**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC
MODEL YEAR : 11/12/2017
ENGINE NO : CVN 045534
CHASSIS NO : WAUZZZF45JA025268
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Aug-22
PLACE OF ACCIDENT : LAVENDER ST AND KALLANG BAHRU

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 2296 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,000.00	
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 4,232.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
[EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 2296 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,609.00	
2	REAR BUMPER FIXING PARTS	1	\$ 480.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00	
5	REAR BUMPER REFLECTOR - RH	1	\$ 46.00	
6	REAR BUMPER CARRIER	1	\$ 1,131.00	
7	REAR BUMPER UPPER IMPACT BAR GASKET - LH / RH	2	\$ 32.00	
8	REAR BUMPER GUIDE SECTION - RH	1	\$ 51.00	
9	REAR BUMPER LOWER GUIDE SECTION LH / RH	2	\$ 52.00	
10	REAR WHEEL HOUSING LINER - RH	1	\$ 260.00	
11	REAR OUTER TAIL LIGHT - RH	1	\$ 1,135.00	
12	RHS REAR RIM	S/N	TBC	
13	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 6,621.00	
TOTAL LABOUR CHARGES		:	\$ 4,232.00	
GRAND TOTAL		:	\$ 10,853.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT