		HS190 T	my not	Aulbrul
	FASTECH AUTO PTE LTD			der
٠.	1 Kaki Bukit Ave 6 #01-48 Autobay			19/8/22
	Singapore 417883			, 10/00
	Tel No: 67452063/ 67467158 Fax No: 6	7458520	2/	5\$7100
	Tax Reg No: 200006262D		/	
	0			Son
	VEHICLE No: SMP 1145X			ľ
1PC	BOOTLID			\$1,655.10 🗶
2PCS	BOOTLID REFLECTORS @\$554.80	72		\$1,109.60 ×
1PC	BOOTLID INNER LOCK TWI	'shold		\$450.10
1PC	BOOTLID INNER TRIM			\$388.90 🗶
2PCS	BOOTLID HINGES @\$175.45			\$350.90 ×
1PC	BOOTLID WEATHERSTRIP 1~1			\$228.61
1PC	BOOTLID OUTER HANDLE 11			\$588.95 🗶
1PC	BOOTLID REAR LOGO NEC		86.10	\$105.00
1PC	BOOTLID 'CAMRY' EMBLEM		***	\$68.80 ×
1PC	BOOTLID 'HYBRID' EMBLEM			\$85.00
1PC	KLAK BOIVIT EK	be		\$1,045.10
1PC	REAR BUMPER LOWER DIFFUSER), 5		\$488.50
1PC	REAR BUMPER BEAM	Bert	499.20	\$7,11.10
2PCS	REAR BUMPER BEAM BRACKETS @\$10			\$210.00
2PCS	REAR BUMPER SIDE RETAINERS @\$72.4			\$144.80
2PCS	REAR BUMPER REFLECTORS @\$100.70	11		\$201.40 ×
1PC	REAR BUMPER UNDER COVER	De/TWI	381.10	\$466.80
2PCS	REAE BUMPER PDC SENSORS @\$480.00	shall	429.10 x 2=858.20	\$1,440.00
1PC	REAR END PANEL	3al5 100	722-10	\$850.10
1PC	REAR END PANEL TOP GARNISH	TWI		\$429.10
2PCS	TAILLAMPS @\$885.10	cm 66	6.90 X2=1333. W	\$1,770.20
2PCS	TAILLAMP LOWER BRACKETS @\$55.90	11		\$111.80
2PCS	TAILLAMP BLACK GARNISHS @\$42.70	11		\$85.40 >
1PC	TAILLAMP HOUSING PANEL O/S	R		\$366.50 X
1PC	REAR FLOOR PANEL	r,		\$1,148.10 X
1PC	REAR FLOOR PANEL TOP BOARD	noged	520.10	\$520.50
1PC	REAR FLOOR PANEL TOOLS SPONGE	ae toin	5-88.20	\$715.10
2PCS	REAR FENDERS @\$1065.30	R	00	\$2,132.60
2PCS	REAR FENDER INNER TRIMS @\$566.10	11		\$1,132.20 🗡
1PC	REAR EXHAUST	11		\$882.10 🗶
1PC	REAR EXHAUST HEAT SHIELD	11		\$150.70 X
2PCS	REAR EXHAUST MOUNTINFS @\$60.00	11		\$120.00 ×
1PC	REAR WINDSCREEN MOULDING	11		\$115.00 🗶
1PC	REAR FENDER UNDER SHIELD O/S	11		\$493.10 ×
1PC	REAR BATTERY HOUSING PANEL O/S	11		\$593.20 ×
1PC	REAR BATTERY SPONGE	17		\$105.20 X
1PC	REAR BATTERY BRACKET	11		\$108.30 🗴
1PC	REAR BATTERY TOP BOARD O/S	11		\$145.10 ×
1PC	REAR ANTENNA SENSOR	eni		\$166.50
1PC	REAR WHEEL HOUSING PANEL O/S	R		\$981.10 🗴

	S.NETT		
1SET	T BOOTLID INNER TRIM CLIPS	\$50.00 🗴	
1SET	T REAR BUMPER CLIPS ne	\$50.00	
1SET	T REAR BUMPER DIFFUSER CLIPS	\$50.00 🗶	
1SET	T REAR REVERSE CAMERA 1	\$380.00 🛚	
1SET	T REAR BUMPER UNDER COVER CLIPS 110	\$50.00	
1PC	REAR END PANEL SEALANT	\$50.00	
1PC	REAR WINDSCREEN SEALANT	\$50.00 🗶	
1PC	REAR WINDSCREEN INNER SEAL	\$50.00 X	
1SET	T REAR FLOOR PANEL INSULATOR	\$480.00 150	
1SET	T REAR FENDER INNER TRIM CLIPS	\$50.00 🗶	
1SET		\$50.00 ×	
1SET	T TAILLAMP CLIPS	\$20.00 ×	
1PC	REAR LICENCE PLATE	\$50.00 €	
	TO CHECK WIRING	\$50.00 30	
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	
	TO DISMANTLE & REFIX BOOTLID MECHANISM	11 \$100.00 X	
	TO DISMANTLE & REFIX REAR WINDSCREEN	イヘ \$150.00 ×	
	TO DISMANTLE & REFIX FUEL TANK	1 ≤ 100.00 ×	
	TO DISMANTLE & REPLACED REAR REVERSE CAMERA	µ~ \$100.00 ×	
	TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00 X	
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	\$250.00 X	
	TO CONDUCT WHEEL ALIGNMENT	12 \$100.00 X	
	TO CONDUCT CHASSIS ALIGNMENT	17 \$380.00 X	
	TO DISMANTLE & REFIX REAR DOOR MECHANISM	イペ \$180.00 X	
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$180.00 <i>& O</i>	
	TO SPRAY RUST PROOFING	\$180.00 &	
	LABOUR FOR PANEL BEATING & REPLACED PARTS	\$3,800.00 /000	
	TO PUTTY & SPRAY PAINTING	\$2,500.00 //00	
		TOTAL COC DOE 40	

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

TOTAL

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$26,925.42 2-8236 17 617736 300 2+20 7117.