





# WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department \ WENG YING (ACCOUNTS

Estimate No: EST2201075

Date: 24 Aug 2022

Policy No: 5124948264

Veh Reg No: PC5082A

Make/Model: TOYOTA HIACE  
SUPER GL DARK  
PRIME 3.0 AUTO

Your Ref No: PC5082A

Chassis No: 1KD2612548

Claim Type: Own Damage

Engine No: KDH2118007109

Accident Date: 23/08/2022

Reg. Date: 28/07/2016

TP Veh Reg No: SH7039B

## Estimate Repair Cost to Vehicle No : PC5082A

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<b>List Price</b>				
1 REAR TAILGATE <i>4/</i>		1 PC	2,941.40	2,941.40
2 REAR TAILGATE HINGE - LH <i>X</i>		1 PC	78.20	78.20
3 REAR TAILGATE HINGE - RH <i>X</i>		1 PC	78.20	78.20
4 REAR TAILGATE OUTER OPENER <i>X</i>		1 PC	443.50	443.50
5 REAR NUMBER PLATE LAMP <i>X</i>		2 PC	58.40	116.80
6 REAR TAILGATE SHOCK ABSORBER - LH <i>X</i>		1 PC	286.20	286.20
7 REAR TAILGATE SHOCK ABSORBER - RH <i>X</i>		1 PC	286.20	286.20
8 REAR TAILGATE INNER TRIM BOARD <i>X</i>		1 PC	248.30	248.30
9 REAR TAILGATE INNER COVER <i>X</i>		1 PC	67.70	67.70
10 REAR TAILGATE 'LOGO' <i>rec /</i>		1 PC	68.10	68.10
11 REAR TAILGATE COVER 'SUPER GL' EMBLE <i>rec /</i>		1 PC	58.20	58.20
12 REAR TAILGATE COVER 'HIACE' EMBLE <i>rec /</i>		1 PC	58.20	58.20
13 REAR TAILGATE INNER LOCK <i>2nd /</i>		1 PC	289.20	289.20
14 REAR TAILGATE LOCK ACTUATOR COVER <i>2nd /</i>		1 PC	89.30	89.30
15 REAR TAILGATE LOCK ACTUATOR <i>X</i>		1 PC	398.40	398.40
16 REAR TAILGATE CATCH <i>X</i>		1 PC	37.70	37.70
17 REAR TAIL GATE STOPPER <i>2nd /</i>		2 PCS	47.80	95.60
18 REAR TAILGATE RUBBER <i>rec /</i>		1 PC	398.60	398.60
19 REAR TAILLAMP LOWER PANEL - RH <i>repair</i>		1 PC	185.20	185.20
20 REAR TAILLAMP PANEL BRACKETS <i>X</i>		2 PC	28.70	57.40
21 REAR END PANEL <i>photo 4/ 5/</i>		1 PC	538.10	538.10
22 REAR END PANEL INNER PANEL <i>2nd /</i>		1 PC	595.90	595.90
23 REAR BUMPER <i>de /</i>		1 PC	752.70	752.70
24 REAR BUMPER SIDE RETAINERS <i>X</i>		2 PCS	96.30	192.60
25 REAR BUMPER BRACKETS <i>X</i>		2 PCS	123.00	246.00
26 REAR CARGO FLOOR PANEL <i>2nd repair</i>		1 PC	2,792.10	2,792.10
27 REAR CARGO FLOOR PANEL END GARNISH <i>2nd /</i>		1 PC	165.60	165.60
28 REAR SPARE TYRE HOLDER <i>X</i>		1 PC	459.20	459.20
29 REAR SPARE TYRE BRACKET <i>X</i>		1 PC	125.60	125.60
30 REAR EXHAUST PIPE <i>X</i>		1 PC	1,267.20	1,267.20
31 REAR EXHAUST PIPE MOUNTING <i>X</i>		1 PC	32.50	32.50
				13,449.90
<b>Special Net</b>				
32 REAR TAILGATE WINDSCREEN GLASS SEALANT		1 PC	100.00	100.00

# WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

**M/S :** AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department \ WENG YING (ACCOUNTS

**Estimate No:** EST2201075

**Date:** 24 Aug 2022

**Policy No:** 5124948264

**Veh Reg No:** PC5082A

**Make/Model:** TOYOTA HIACE HIACE

SUPER GL DARK

PRIME 3.0 AUTO

**Your Ref No:** PC5082A

**Chassis No:** 1KD2612548

**Claim Type:** Own Damage

**Engine No:** KDH2118007109

**Accident Date:** 23/08/2022

**Reg. Date:** 28/07/2016

**TP Veh Reg No:** SH7039B

## Estimate Repair Cost to Vehicle No : PC5082A

Description	U/Price	Quantity	Cost	Amount
			<b>S\$</b>	<b>S\$</b>
33 REAR TAIL GATE OUTER OPENER CLIPS X		1 PC	45.00	45.00
34 REAR TAILGATE INNER TRIM BOARD CLIPS M		1 SET	75.00	40 75.00
35 REAR TAILGATE '70km/h' STICKER M		1 PC	15	10 15.00
36 REAR BUMPER CLIPS M		1 SET	65.00	40 65.00
37 REAR BUMPER REVERSE SENSOR M		1 SET	200.00	200.00
38 REAR BUMPER PROTECTOR MOULDING M		1 SET	50.00	30 50.00
39 REAR NUMBER PLATE (SMART) X		1 PC	45.00	45.00
1 'Emergency Door' sticker M		1 pc	\$15 to 12	595.00
<b>Labour</b>				750 1000
40 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS, JACK, STRAIGHTEN, CUT, WELD, REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,400.00	1,400.00
41 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED		1 JOB	1,400.00	750 1000 1,400.00
42 WIRING JOB		1 JOB	45	30 45.00
43 LABOUR TO REMOVE AND REFIX REAR WINDSCREEN GLASS.		1 JOB	130	120 130.00
44 LABOUR TO INSTALL NEW REAR BUMPER REVERSE SENSOR ONTO NEW BUMPER		1 JOB	60	60.00
45 LABOUR TO REMOVE REAR EXHUAUST PIPE ENABLE NECESSARY REPLACE AND REPAIR WORKS		1 JOB	150.00	X 150.00
46 LABOUR TO TRANSFER OF DAMAGED REAR TAILGATE ATTACHMENTS TO NEW TAILGATE		1 JOB	80.00	80.00
47 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	150.00	60 150.00
				3,415.00

# WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapisp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department \ WENG YING (ACCOUNTS

Estimate No: **EST2201075**

Date: 24 Aug 2022

Policy No: 5124948264

Veh Reg No: **PC5082A**

Make/Model: TOYOTA HIACE HIACE  
SUPER GL DARK  
PRIME 3.0 AUTO

Your Ref No: PC5082A

Claim Type: Own Damage

Accident Date: 23/08/2022

TP Veh Reg No: SH7039B

Chassis No: 1KD2612548

Engine No: KDH2118007109

Reg. Date: 28/07/2016

## Estimate Repair Cost to Vehicle No : PC5082A

Total S\$ 17,459.90

Add GST @ 7% 1,222.19

Total Amount payable S\$ 18,682.09

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND SIX HUNDRED EIGHTY TWO AND CENTS NINE ONLY

For WILLIAM'S AUTO PTE LTD



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

#p90010068

7 days

45

30/08/22 @ 1215

Reg after repair



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	24/08/2022 14:55 (SGT)
Reported by	Driver
Date of Accident	23/08/2022 18:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TOH GUAN ROAD TO PIE (CHOA CHU KANG)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC5082A
-----------------------------	---------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	ACE @ WORK ENRICHMENT PTE. LTD
Company Reg No	201200122M
Email Address	CYNTHIA@ACEATWORK.COM.SG
Mobile Phone No	(Phone) +65-90606517
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	2982

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number	5124948264

### DRIVER

Name of Driver	LEE CHEE CHONG
NRIC No	S2511200H
Date Of Birth	08/10/1959
Occupation	Outdoor

Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

30/03/1979  
43 YEARS AND 5 MONTHS  
Male  
(Phone) +65-90606517  
-  
CYNTHIA@ACEATWORK.COM.SG  
BLK 675 CHOA CHU KANG CRESCENT #06-433  
-  
680675  
No  
Employee  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### PASSENGER 1

Name  
Gender

IRENE LAI KWEE ENG  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

MY VEHICLE WAS STOPPED ALONG THE JUNCTION OF TOH GUAN ROAD ON THE LEFT LANE WAITING FOR THE RED LIGHT AHEAD. ALL OF A SUDDEN, I FELT A GREAT IMPACT AND LOUD BANG COMING FROM THE REAR PORTION OF MY VEHICLE. I THEN ALIGHTED TO CHECK AND REALISED THAT THE TAXI SH7039B BEHIND ME HAD FAILED TO CONTROL TO BRAKE ON TIME AND THUS THE FRONT PORTION OF THE TAXI COLLIDED ONTO THE REAR PORTION OF MY STATIONED VEHICLE CAUSING DAMAGE TO MY VEHICLE

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?

Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SH7039B

Accident report SN07228O000Y



Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	KOH KAH TIAN
NRIC No	S1217425Z
Contact Number	(Phone) +65-98169030
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3



## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature, Date & Time

24/08/2022  
Sketch Plan 15:00h

Driver's Signature (if driver is not the policyholder) / Date

24/08/2022  
15:00h

Witnessed by Reporting Centre Personnel:

(Name as in NRIC/ID card)

Mohamed Yusof

199599

Bin Abdul Samad

PIE

A - PCS0824

B - SH 7039B



Toh Guan Road



Describe Circumstance of the Accident

Refer to gears

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

24/08/2022  
1500hrs

Driver's Signature (if driver is not the policyholder) / Date & Time

24/08/2022  
1500hrs

Witnessed by Reporting Centre Personnel

(Name as in NRIC ID card)

Mohammed Yusof Bin  
Abdul Samad  
Soy 9957

2



**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : SN072280000Y Vehicle Registration No: P65083 A  
Name (as shown in NRIC) : Lee Chee Chang NRIC/FIN/Passport No : S2511200H  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : BLK 675 CHOA CHU KANG CRESCENT # Singapore (680675)  
05-433  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 96606579  
Email Address : CYNTHIA@ACEATWORK.COM.SG  
Date of Accident : 23/08/2022 Time of Accident : 6:20pm  
Place of Accident : Junction of Toh Guan Rd to PIE (Choa Chu Kang)  
Insurance Company : NIC

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To change accident location to Toh Guan Rd to  
PIE (Choa Chu Kang)  
Third Party Vehicle number should be S117029B



Policyholder / Driver's Signature  
Date: 25/08/2022





Reporting Centre Personnel's Signature  
Name: MOHAMMAD YUNUS BIN ABDUL SAMAD  
NRIC/FIN No : S099951  
Date: 25/08/2022



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	122M
Vehicle No.:	PC5082A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE SUPER GL DARK PRIME 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2612548
Chassis No.:	KDH2118007109
Maximum Power Output:	-
Open Market Value:	\$50,568.00
Original Registration Date:	28 Jul 2016
First Registration Date:	28 Jul 2016
Transfer Count: -	1
Actual ARF Paid:	\$2,529.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	27 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$18,437.00
Total Rebate Amount:	\$18,437.00

The information contained herein is correct as at 31 Aug 2022

OK



# Toyota Hiace 3.0A Super GL Dark Prime

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	<b>\$56,800</b>	Lifespan ⓘ	19-Oct-2036
Depreciation ⓘ	\$13,730 /yr <a href="#">View models with similar depre</a>	Reg Date	20-Oct-2016 (4yrs 1mth 18days COE left)
Mileage	N.A.	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$2,071 as of today (change)	Fuel Type	Diesel
COE ⓘ	\$5,006	OMV ⓘ	\$45,864
Engine Cap	2,982 cc	ARF ⓘ	\$2,294
Curb Weight ⓘ	1,800 kg	No. of Owners ⓘ	3
Type of Vehicle	Van		

## Features

[View specs of the Toyota Hiace](#)