

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01

AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department \ WENG YING (ACCOUNTS

Estimate No: EST2201075

Date: 24 Aug 2022

Policy No: 5124948264

Veh Reg No: PC5082A

Make/Model: TOYOTA HIACE HIACE
SUPER GL DARK
PRIME 3.0 AUTO

Your Ref No: PC5082A

Chassis No: 1KD2612548

Claim Type: Own Damage

Engine No: KDH2118007109

Accident Date: 23/08/2022

Reg. Date: 28/07/2016

TP Veh Reg No: SH7039B

Estimate Repair Cost to Vehicle No : PC5082A

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR TAILGATE <i>4/ 1698</i>		1 PC	2,941.40	2,941.40
2 REAR TAILGATE HINGE - LH <i>X</i>		1 PC	78.20	78.20
3 REAR TAILGATE HINGE - RH <i>X</i>		1 PC	78.20	78.20
4 REAR TAILGATE OUTER OPENER <i>X</i>		1 PC	443.50	443.50
5 REAR NUMBER PLATE LAMP <i>X</i>		2 PC	58.40	116.80
6 REAR TAILGATE SHOCK ABSORBER - LH <i>X</i>		1 PC	286.20	286.20
7 REAR TAILGATE SHOCK ABSORBER - RH <i>X</i>		1 PC	286.20	286.20
8 REAR TAILGATE INNER TRIM BOARD <i>X</i>		1 PC	248.30	248.30
9 REAR TAILGATE INNER COVER <i>X</i>		1 PC	67.70	67.70
10 REAR TAILGATE 'LOGO' <i>rec /</i>		1 PC	68.10	68.10
11 REAR TAILGATE COVER 'SUPER GL' EMBLE <i>rec /</i>		1 PC	58.20	58.20
12 REAR TAILGATE COVER 'HIACE' EMBLE <i>rec /</i>		1 PC	58.20	58.20
13 REAR TAILGATE INNER LOCK <i>2nd /</i>		1 PC	289.20	289.20
14 REAR TAILGATE LOCK ACTUATOR COVER <i>2nd /</i>		1 PC	89.30	89.30
15 REAR TAILGATE LOCK ACTUATOR <i>X</i>		1 PC	398.40	398.40
16 REAR TAILGATE CATCH <i>X</i>		1 PC	37.70	37.70
17 REAR TAIL GATE STOPPER <i>2nd /</i>		2 PCS	47.80	95.60
18 REAR TAILGATE RUBBER <i>rec / 340</i>		1 PC	398.60	398.60
19 REAR TAILLAMP LOWER PANEL - RH <i>repair</i>		1 PC	185.20	185.20
20 REAR TAILLAMP PANEL BRACKETS <i>X</i>		2 PC	28.70	57.40
21 REAR END PANEL <i>photo 4/ 51</i>		1 PC	538.10	538.10
22 REAR END PANEL INNER PANEL <i>2nd / 51</i>		1 PC	595.90	595.90
23 REAR BUMPER <i>de - 651</i>		1 PC	752.70	752.70
24 REAR BUMPER SIDE RETAINERS <i>X</i>		2 PCS	96.30	192.60
25 REAR BUMPER BRACKETS <i>X</i>		2 PCS	123.00	246.00
26 REAR CARGO FLOOR PANEL <i>2nd repair</i>		1 PC	2,792.10	2,792.10
27 REAR CARGO FLOOR PANEL END GARNISH <i>2nd</i>		1 PC	165.60	165.60
28 REAR SPARE TYRE HOLDER <i>X</i>		1 PC	459.20	459.20
29 REAR SPARE TYRE BRACKET <i>X</i>		1 PC	125.60	125.60
30 REAR EXHAUST PIPE <i>X</i>		1 PC	1,267.20	1,267.20
31 REAR EXHAUST PIPE MOUNTING <i>X</i>		1 PC	32.50	32.50
				13,449.90

25%

Special Net

32 REAR TAILGATE WINDSCREEN GLASS SEALANT

1 PC

100.00

100.00 **50**
NEL

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department \ WENG YING (ACCOUNTS

Estimate No: EST2201075

Date: 24 Aug 2022

Policy No: 5124948264

Veh Reg No: PC5082A

Make/Model: TOYOTA HIACE
HIACE
SUPER GL DARK
PRIME 3.0 AUTO

Your Ref No: PC5082A

Claim Type: Own Damage

Accident Date: 23/08/2022

TP Veh Reg No: SH7039B

Chassis No: 1KD2612548

Engine No: KDH2118007109

Reg. Date: 28/07/2016

Estimate Repair Cost to Vehicle No : PC5082A

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
33 REAR TAIL GATE OUTER OPENER CLIPS X		1 PC	45.00	45.00
34 REAR TAILGATE INNER TRIM BOARD CLIPS X		1 SET	75.00	40 75.00
35 REAR TAILGATE '70km/h' STICKER X		1 PC	15	10 15.00
36 REAR BUMPER CLIPS X		1 SET	65.00	40 65.00
37 REAR BUMPER REVERSE SENSOR X		1 SET	200.00	200.00
38 REAR BUMPER PROTECTOR MOULDING X		1 SET	50.00	30 50.00
39 REAR NUMBER PLATE (SMART) X		1 PC	45.00	45.00
Emergency Door Sticker X		1 pc	\$15 to 12	595.00
Labour				750 1000
40 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS, JACK, STRAIGHTEN, CUT, WELD, REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,400.00	1,400.00
41 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED		1 JOB	1,400.00	750 1000
42 WIRING JOB		1 JOB	45	30 45.00
43 LABOUR TO REMOVE AND REFIX REAR WINDSCREEN GLASS.		1 JOB	130	120 130.00
44 LABOUR TO INSTALL NEW REAR BUMPER REVERSE SENSOR ONTO NEW BUMPER		1 JOB	60	60.00
45 LABOUR TO REMOVE REAR EXHAUST PIPE ENABLE NECESSARY REPLACE AND REPAIR WORKS		1 JOB	150.00	X 150.00
46 LABOUR TO TRANSFER OF DAMAGED REAR TAILGATE ATTACHMENTS TO NEW TAILGATE		1 JOB	80.00	80.00
47 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	150.00	60 150.00
				3,415.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 68804838,68804572
ATTN: Motor Claim Department \ WENG YING (ACCOUNTS)

Estimate No: **EST2201075**
Date: 24 Aug 2022
Policy No: 5124948264
Veh Reg No: **PC5082A**
Make/Model: TOYOTA HIACE HIACE
SUPER GL DARK
PRIME 3.0 AUTO
Chassis No: 1KD2612548
Engine No: KDH2118007109
Reg. Date: 28/07/2016

Your Ref No: PC5082A
Claim Type: Own Damage
Accident Date: 23/08/2022
TP Veh Reg No: SH7039B

Estimate Repair Cost to Vehicle No : PC5082A

Total	S\$ 17,459.90
Add GST @ 7%	1,222.19
Total Amount payable	<u>S\$ 18,682.09</u>

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND SIX HUNDRED EIGHTY TWO AND CENTS NINE ONLY

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
#p90010068
7 days
4/5
30/08/22 @ 1215
Reg after repair