



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 8383T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (WCP)	BENT	1,160.00	1,160.00
1	FRONT FENDER ARCH TRIM LH (WCP)	NECESSARY	130.00	130.00
1	FRONT FENDER ARCH TRIM RH (WCP)	NECESSARY	155.00	155.00
1	FRONT BUMPER (WCP)	BENT	845.00	845.00
1	FRONT BUMPER INNER CENTRE PART (WCP)	CRACKED	130.00	130.00
1	FRONT BUMPER LOWER CENTRE SURROUND CHROME (WCP)	DENTED	280.00	280.00
1	FRONT NUMBER PLATE BASE (WCP)	DENTED	82.00	82.00
1	RADIATOR GRILLE (WCP)	CRACKED	130.00	130.00
1	RADIATOR GRILLE MOULDING (WCP)	CRACKED	135.00	135.00
1	RADIATOR GRILLE LOGO EMBLEM (WCP)	NECESSARY	65.00	65.00
1	GRILLE AIR GUIDE RH (WCP)	SERVICEABLE	35.00	-
1	AC DECAL (WCP)	NECESSARY	35.00	35.00
1	RADIATOR GRILLE TRIM CHROME RH UPPER (WCP) (ADDITIONAL)	NECESSARY	45.00	45.00
1	RADIATOR GRILLE TRIM CHROME RH LOWER (WCP) (ADDITIONAL)	NECESSARY	45.00	45.00
1	BONNET BUFFER STOP RH (WCP) (ADDITIONAL)	CRACKED	16.00	16.00
1	BONNET SPRING STOPPER RH (WCP) (ADDITIONAL)	NECESSARY	20.00	20.00
	COST PLUS 15%		496.20	490.95
			3,804.20	3,763.95
19	FRONT BUMPER TRIP-GRIP RIVETS @\$4.00 (SN)	NECESSARY	76.00	76.00
	COST PLUS 15%		11.40	-
			87.40	76.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
			40.00	40.00
<u>LABOUR</u>				
	TO CHECK/CLEAR FAULT CODES AFTER REPAIR.		120.00	120.00

Report Ref No. CS/LPC22008361/Kcy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO KNOCK DENTS ON FRONT SUPPORT PANEL AND RENEW OF PARTS.		500.00	450.00
	TO SPRAY PAINT.		700.00	650.00
			1,320.00	1,220.00
GRAND TOTAL			5,251.60	5,099.95
RECOMMENDED COST OF REPAIRS				5,099.95

Report Ref No. CS/LPC22008361/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.