

Vehicle Damage Assessment Report for [SH8575M]

Estimate Created: 12/01/2023 09:53 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 12/01/2023 10:30 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SH8575M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$29,353.58 WITH 11 DAYS

Insurlogic 5 (12/01/2023 10:30)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT DOOR COMFORT LOGO		1	105.00	-25.00 %	78.75
BONNET		1	1330.70	-25.00 %	998.03
INSULATOR HOOD		1	557.34	-25.00 %	418.01
INSULATOR CLIP		10	5.04	-25.00 %	37.80
BONNET RUBBER		1	49.70	-25.00 %	37.28
BONNET HINGE RH		1	80.78	-25.00 %	60.59
BONNET HINGE LH		1	80.78	-25.00 %	60.59
BONNET LOCK		1	185.64	-25.00 %	139.23
RADIATOR GRILLE		1	316.87	-25.00 %	237.65
RADIATOR GRILLE EMBLEM		1	79.35	-25.00 %	59.51
RADIATOR GRILLE EMBLEM LOWER GARNISH		1	120.37	-25.00 %	90.28
FRONT BUMPER COVER G5		1	586.18	-25.00 %	439.64
FRONT BUMPER REINFORCEMENT		1	716.60	-25.00 %	537.45
FRONT BUMPER SPONGE		1	110.32	-25.00 %	82.74
FRONT BUMPER LOWER GRILLE		1	208.04	-25.00 %	156.03
LAMP ASSY, FOG RH		1	961.70	-25.00 %	721.28
FRONT NO. PLATE GARNISH		1	89.60	-25.00 %	67.20
FRONT BUMPER CLIP		1	30.80	-25.00 %	23.10
FRONT BUMPER SIDE RETAINER O/S		1	77.00	-25.00 %	57.75
FRONT BUMPER TOP GARNISH		1	225.40	-25.00 %	169.05
COVER, FRONT BUMPER HOLE O/S		1	39.73	-25.00 %	29.80
FRONT BUMPER LOWER REINFORCEMENT		1	330.54	-25.00 %	247.91
HEADLAMP UNIT LH/RH (LED)		2	2735.28	-25.00 %	4,102.92
HEADLAMP ECU O/S		1	682.60	-25.00 %	511.95
HEADLAMP PANEL LH/RH		2	240.10	-25.00 %	360.15
TOP PANEL CENTRE		1	364.98	-25.00 %	273.74
TOP PANEL SIDE O/S		1	204.26	-25.00 %	153.20
BRACE PANEL		1	105.28	-25.00 %	78.96
RADIATOR ASSY		1	1841.80	-25.00 %	1,381.35
RADIATOR FAN MOTOR ASSY		1	925.82	-25.00 %	694.37

RADIATOR TOP HOSE	1	60.24	-25.00 %	45.18
RADIATOR SPARE TANK	1	176.12	-25.00 %	132.09
HOSE	1	157.79	-25.00 %	118.34
AIR CLEANER HOUSING ASSY	1	836.70	-25.00 %	627.53
AIR DUCT	1	181.16	-25.00 %	135.87
CONDENSER ASSY, W/RECEIVER	1	1336.60	-25.00 %	1,002.45
AIRCON DISCHARGE HOSE	1	386.90	-25.00 %	290.18
AIRCON LIQUID HOSE & PIPE	1	580.45	-25.00 %	435.34
AIRCON HOSE SUCTION	1	541.87	-25.00 %	406.40
FENDER SUB-ASSY, FRONT RH	1	1111.93	-25.00 %	833.95
FRONT FENDER SHIELD RH	1	277.90	-25.00 %	208.43
FRONT FENDER SHIELD CLIP	1	20.86	-25.00 %	15.65
FRONT FENDER HYBRID EMBLEM RH	1	86.50	-25.00 %	64.88
FRONT WINDSCREEN GLASS	1	1627.30	-25.00 %	1,220.48
FRONT WINDSCREEN GLASS MOULDING	1	208.60	-25.00 %	156.45
ARM, FRONT WIPER RH	1	252.14	-25.00 %	189.11
WIPER TOP GARNISH	1	686.90	-25.00 %	515.18
WIPER SPARE TANK	1	257.25	-25.00 %	192.94
WIPER SPARE TANK MOTOR	1	339.78	-25.00 %	254.84
WIPER SPARE TANK FLOAT (NECK)	1	77.70	-25.00 %	58.28
ENGINE MOUNTING RH	1	382.70	-25.00 %	287.03
ENGINE TOP COVER	1	260.00	-25.00 %	195.00
BRAKE MASTER PUMP	1	5281.20	-25.00 %	3,960.90
BONNET STAND	1	285.72	-25.00 %	214.29
FRONT LOWER CROSSMEMBER	1	320.65	-25.00 %	240.49
RADIATOR RETURN HOSE INLET	1	160.24	-25.00 %	120.18
RADIATOR RETURN HOSE OUTLET	1	159.64	-25.00 %	119.73
FRONT WINDSCREEN LOWER MOULDING	1	185.45	-25.00 %	139.09
WIPER TOP GARNISH PANEL	1	1125.38	-25.00 %	844.04
ENGINE VALVE COVER	1	1568.58	-25.00 %	1,176.44

ENGINE VALVE COVER RUBBER	1	268.85	-25.00 %	201.64
------------------------------	---	--------	----------	--------

Parts Subtotal 26,708.71

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT NUMBER PLATE		1.0	45.00	0.00 %	45.00
FRONT WINDSCREEN SEALANR		1.0	40.00	0.00 %	40.00

Materials Subtotal 85.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BAETING	RnR	1400.00	0.00 %	1,400.00
WIRING CHARGE	RnR	30.00	0.00 %	30.00
TUFF KOTE	RnR	40.00	0.00 %	40.00
REMOVE/REFIX RADIATOR	RnR	50.00	0.00 %	50.00
REMOVE/REFIX AIRCON & REFILL GAS	RnR	80.00	0.00 %	80.00
REMOVE/REFIX FRONT WINDSCREEN GLASS	RnR	80.00	0.00 %	80.00
REMOVE/REFIX BRAKE MASTER & BOOSTER PUMP	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING CHARGE	Full spray	800.00	0.00 %	800.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,760.00

Paint Labor Subtotal 800.00

Labor Subtotal 2,560.00

Summary

Repair Cost 29,353.71

Discount(0 %) (0.00)

29,353.71

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 29,353.71