

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBM 2656C
 at Workshop m/s Enfa
 of _____
 Insured: SMV 60084
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: \$ 8k.
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LTA 2739 Vehicle: IN / OUT

Veh No: FBM 2656C Yr Regn: 11/09/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha Tricity c.c. 155
 Colour: Blue #C: Insured / Std / NI / NA
 Sp. Reading: 31836 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MLESH381000056610
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or steered
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 90-80-14
 R: 130-70-13
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or shinko
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. _____ mm
 D.O.A. 30/07/22 D.O.I. 30/8/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rt, N/S Lft
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
23/12/22 Rep 1600 NHT \$5261
1/5 \$4200 informed MR Teo.
(Red. \$442.60, 51%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 2

1) 23/12/22
 Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : TP
 Lump Sum / I.B.I: (\$ 4200)

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	214A
Vehicle Details	
Vehicle No.:	FBM2656C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2022
Vehicle Make:	YAMAHA
Vehicle Model:	TRICITY 155 ABS
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G3H3E056610
Chassis No.:	MLESG381000056610
Maximum Power Output:	-
Open Market Value:	\$4,102.00
Original Registration Date:	11 Sep 2017
First Registration Date:	11 Sep 2017
Transfer Count:	1
Actual ARF Paid:	\$616.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Sep 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,402.00
COE Rebate Amount:	\$2,739.00
Total Rebate Amount:	\$2,739.00

The information contained herein is correct as at 15 Aug 2022

OK

Advertisement

Motorcycles > Motorcycles for Sale > Class 2B



Tricity 155 ABS (Used)

ASPHOON PTE LTD ♣️ CHANGI ♣️ ...

Cars & Property Fashion Home & Living Electronics & Mobiles Hobbies & Games Jobs & Services Oth Register Login



Search for an item

All of Singapore

Chat

Sell

Description

Bumped	Make	Type
18 hours ago	Yamaha	Scooter

Original Registration Year : 2017
 COE Expired : November 2027
 One Owner Before

Our Company NO
 No Hidden Cost
 No Early Repayment Penalty

read more

Write a custom message...

Hi, is this still available?

Is the price negotiable?

Can I see more photos?

Sign in to make offer



S\$ 7800

Make Offer

Advertisement

Meet-up

Changi Road

Meet the seller



ASPHOON PTE LTD ♣️ CHANGI ♣️

@onn99

Joined 4 years ago

Very Responsive

Advertisement

Privacy - Terms

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 02503

Date: 11/8/22

Particular: _____

Vehicle No: FBM 2656 C Model No: TRICITY

From: 178 Paya Lebar To: SROEIA

Time: (Day/Night): _____

Others: _____

CASH \$: 60/-

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Auto General

Name : Foo Kia Mee (92961609)

Accident Date : 30-Jul-22

Vehicle No : FBM2656C (COE100927)

Vehicle Model : Yamaha Tricity
155ABS

Estimated Repair Costs

Qty	Description		Amount S(\$)	
<u>List Items</u>				
2	Front fork tube assy - L/H	<i>sent/1w1</i>	900	\$ 1,050.00 ✓
2	Front fork tube assy - R/H	<i>11</i>		\$ 1,050.00 X
1	Fork under bracket	<i>sent</i>		\$ 360.00 ✓
1	Front fender - L/H	<i>DI</i>		\$ 138.00 ✓
1	Front fender - L/H (Matt)	<i>DI</i>	110	\$ 128.00 ✓
1	Front wheel rim - L/H	<i>cut</i>		\$ 480.00 ✓
1	Front rim shaft	<i>11</i>		\$ 78.00 X
1	Front rim bearing	<i>net</i>		\$ 62.00 ✓
1	Front brake disc	<i>17</i>		\$ 298.00 X
1	Handle-bar	<i>sent</i>		\$ 228.00 ✓
1	Hand grip (1 set)	<i>cut</i>		\$ 48.00 ✓
1	Handle bar ends	<i>DI</i>		\$ 75.00 ✓
1	Headlamp assy	<i>cut</i>	1200	\$ 1,500.00 ✓
1	Side mirrors - L/H	<i>cut</i>		\$ 68.00 ✓
1	Brake lever	<i>cut</i>		\$ 90.00 ✓
2	Front signals	<i>DI cut</i>	75	\$ 212.00 12c
1	Front cowling	<i>cut</i>		\$ 220.00 ✓
1	Front cover - matt	<i>cut</i>		\$ 215.00 ✓
1	Front side cover - matt	<i>cut</i>	80	\$ 120.00 ✓
1	Footstep lower panel	<i>cut</i>		\$ 200.00 ✓
1	Rear side fairing	<i>cut</i>	165	\$ 168.00 ✓
2	Air filter cover	<i>11</i>		\$ 165.00 X
1	Drove belt cover	<i>cut</i>		\$ 185.00 ✓
2	Side stand	<i>11</i>		\$ 138.00 X
1	Main stand	<i>cut</i>	175	\$ 228.00 ✓
				\$ 7,504.00
			Less 10%	\$ 750.40
				\$ 6,753.60

not authorized
hr

30/8/22

2/5 4200

take photo after repair
H. J. S.

5074
10%
4866.6

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Foo Kia Mee (92961609)

Accident Date : 30-Jul-22

Vehicle No : FBM2656C (COE100927)

Vehicle Model : Yamaha Tricity
155ABS

Estimated Repair Costs

Special Nett Items


1	Number plate (1 set) 11	\$	38.00	X
2	Fork oils 11	\$	30.00	X
2	Fork oil seals 11	\$	56.00	X
1	Steering cone (1 set) 111	\$	95.00	✓
1	Rear box 647	\$	480.00	300
1	Rear box bracket 11	\$	180.00	X
		\$	879.00	

S/No. Labour

1	To provide towing serving (LOD) S\$60.00	\$	-	
2	To check wiring and reset headlamp focusing	\$	11 80.00	X
3	To repair body frame	\$	11 480.00	X
4	To provide labour	\$	450.00	380
		\$	1,010.00	

Grand Total \$ **8,642.60**

Singapore Dollars: Eight Thousand Six Hundred Forty-Two and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5701-6