

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

30/8/2022

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA SIENTA - SLR8286C

DOA : 27/08/2022

not Authorized
31/08/22
4/5 \$3000/
5 days.

S/N	QTY	DESCRIPTION		
1	1 PC	REAR TAILGATE	\$	1221.80
2	1 PC	REAR BUMPER TOP - RH	\$	485.00 X
3	1 PC	REAR BUMPER LOWER	\$	452.20
4	1 PC	REAR BUMPER SIDE GARNISH - RH	\$	139.30
5	1 PC	REAR BUMPER REFLECTOR - RH	\$	65.00
6	1 PC	REAR WINDSCREEN MOULDING	\$	104.40
7	1 PC	REAR TAILGATE WEATHERSTRIP	\$	402.50
8	1 PC	REAR BUMPER SIDE RETAINER - RH	\$	108.70 X
9	1 PC	END PANEL	\$	469.60
			\$	3448.50
			Disc -25%	\$ -862.12
			\$	2586.38
10	1 SET	REVERSE SENSOR	\$	280.00 200 s/w
11		L/B FOR REVERSE SENSOR	\$	80.00 50
12		LABOUR CHARGE	\$	1200.00 600
13		SPRAY PAINTING	\$	1500.00 850
14		WIRING	\$	35.00 20
15		TUFF COAT	\$	100.00 30
16		REMOVE & REFIX W/S Rear windscreen	\$	120.00 ✓
17		REMOVE CARPET & GARNISH	\$	180.00 60
			\$	6081.38
			Total	\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2452.3
252
1839.22
3769.22