

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0749/2022/EQ
DATE	:	30-Aug-22
WIP	:	39545

xiao teng.

SGX 5202S.

\$4108.80.

03 Aug.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/8/2022

YOUR INSURED VEH NO : SNA 3157 R

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME	:	MR. ANG PUAY HIN
ADDRESS	:	145 PASIR RIS GROVE
		#13-65
		SINGAPORE 518137
TELEPHONE	:	HP +65 85226742
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	SP2001869707-01
VEHICLE NO	:	SGX 5202 S
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR	:	28/5/2018
ENGINE NO	:	CVK 060672
CHASSIS NO	:	WAUZZZF40JA159895
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	27-Aug-22
PLACE OF ACCIDENT	:	ALONG CTE NEAR EXIT TO PIE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 5202 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	500
3	TO RESPRAY REAR BUMPER	\$	900.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	2,502.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 5202 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rebond</i>	1	\$ 2,609.00	<i>✓</i> 2,087.20
2	REAR BUMPER FIXING PARTS <i>New</i>	1	\$ 480.00	<i>+</i>
3	REAR BUMPER SECURING STRIP <i>New</i>	1	\$ 249.00	<i>✓</i> 198.80
4	REAR BUMPER SPOILER <i>Rebond</i>	1	\$ 276.00	<i>✓</i> 220.80
5	REAR BUMPER REFLECTOR - LH / RH <i>New</i>	2	\$ 92.00	<i>+</i>
6	REAR BUMPER CARRIER <i>New</i>	1	\$ 1,131.00	<i>+</i>
7	REAR BUMPER UPPER IMPACT BAR GASKET - LH / RH <i>New</i>	2	\$ 32.00	<i>+</i>
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00	<i>+</i>
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	<i>+</i>
10	REAR PARKING AID SEAL RING	4	\$ 10.00	<i>+</i>
11	SUNDRIES <i>New</i>		\$ 300.00	<i>+</i>
TOTAL SPARE PARTS		:	\$ 5,762.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 8,264.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
31/08/22

Not Authorised, 03 Days H/S

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT