

Date : 29/08/2022

TO: **AIG Asia Pacific Insurance Pte Ltd**  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120

Our Customer : Geetha D/O Kunasegar

Vehicle No : SJX6751G

Model : Kia Cerato Forte 1.6SX

Manufacture Year : 2010

Date of Accident : 07/08/2022

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claim Department

Fax : 6415 3727

KNAFW411MAS255960

Re: Repair Estimate For Third Party Claim against SKZ6127L

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Rear bumper <i>Rehnd</i>	1	\$651.00	\$651.00	✓
2	Rear bumper pad <i>Rehnd</i>	1	\$530.00	\$530.00	231
3	Rear bumper side retainer RH <i>3M</i>	1	\$38.30	\$38.30	✓
4	Rear bumper side retainer LH <i>3M</i>	1	\$38.30	\$38.30	✓
5	Rear bumper reinforcement <i>Rehnd</i>	1	\$527.00	\$527.00	304
6	Rear bumper foam <i>Rehnd</i>	1	\$174.00	\$174.00	108
7	Rear end panel <i>Rehnd</i>	1	\$452.00	\$452.00	✓
8	Rear end panel garnish <i>Rehnd</i>	1	\$99.80	\$99.80	x
9	Tail lamp RH <i>Rehnd</i>	1	\$462.60	\$462.60	x
10	Boot lid <i>Rehnd</i>	1	\$1,782.00	\$1,782.00	948
11	Boot lid weatherstrip <i>Rehnd</i>	1	\$99.80	\$99.80	x
12	Boot lid "Kia" logo <i>Rehnd</i>	1	\$38.80	\$38.80	✓
13	Boot lid lock <i>Rehnd</i>	1	\$186.20	\$186.20	✓
14	Spare tyre panel <i>Rehnd</i>	1	repair	repair	✓
15	Exhaust chrome <i>Rehnd</i>	1	\$98.00	\$98.00	✓
16	Exhaust silencer <i>Rehnd</i>	1			✓
17	Rear fender RH <i>Rehnd</i>	1	repair	repair	✓
	<i>2595.60</i>		<b>Sub Total</b>	<b>\$5,177.80</b>	
	<i>2696.64</i>		Less 10%	\$517.78	
			<b>Sub Total 1</b>	<b>\$4,660.02</b>	
<b>A.</b>	<b>Spare Parts (S/Nett)</b>				
1	Reverse sensor <i>Rehnd</i>	1	\$250.00	\$250.00	200
2	Rear bumper clip <i>Rehnd</i>	10	\$5.00	\$50.00	30
3	Rear end panel garnish clip <i>Rehnd</i>	10	\$5.00	\$50.00	✓
				\$0.00	
			<b>Sub Total 2</b>	<b>\$350.00</b>	230
			<b>Total Spare Parts</b>	<b>\$5,010.02</b>	
<b>B.</b>	<b>Labour</b>				
1	To check wiring.			\$80.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	200
3	Spray painting all affected parts & areas.			\$1,200.00	600

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
4	To spray anti-rust undercoat.			\$90.00	X 60
5	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$200.00	7 30
6	To remove and replace exhaust silencer.			\$250.00	X
	<b>Total Labour</b>			<b>\$2,820.00</b>	
	<b>Total Repair Cost</b>			<b>\$7,830.02</b>	

1420-

Adrian Ling  
H/S 01/09/22

03 Days

Yours faithfully,

Aun Teng  
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

total: 4346.04  
L/S: 3.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: