

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

3/9/2022

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR VOLVO XC60 - SJB8881S

DOA :27/08/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
H/S 8900/
H/S
changed the 14
8/9/22

S/N	QTY	DESCRIPTION			
1	1 PC	REAR BUMPER	cut/	2425	\$ 2895.00
2	10 PCS	REAR BUMPER CLIPS	new	60	\$ 80.00
3	1 PC	REAR BUMPER LH SIDE RETAINER	an		\$ 215.00
4	1 PC	REAR LH FENDER	sub m		\$ 3465.00
5	1 PC	REAR LH FENDER SHIELD	Torn	205	\$ 250.00
6	1 PC	REAR LH RIM	cut	980	\$ 1450.00
7	1 PC	REAR LH DOOR	sub m	3130	\$ 3760.00
8	1 PC	REAR LH TRIM RUBBER	an		\$ 48.00
9	1 PC	LH SIDE SKIRT	R		\$ REPAIR
10	1 PC	REAR LH FENDER QUARTER GLASS MOULDING	an		\$ 367.00
					\$ 12530.00
				Disc -10%	\$ -1253.00
					\$ 11277.00
		SPRAY PAINTING			\$ 1100.00
		LABOUR CHARGE			\$ 1480.00
		QUARTER GLASS SEALANT			\$ 40.00
		QUARTER GLASS LABOUR			\$ 120.00
		REMOVE & REFIX CARPET AND GARNISHES			\$ 120.00
		TUFF COAT			\$ 100.00
		WHEEL ALIGNMENT			\$ 100.00
					\$ 14337.00
				Total	\$ 14337.00

10265
102
9238.5
11178.50