

Vehicle Damage Assessment Report for [SJP8676U]

Estimate Created: 30/08/2022 02:19 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/02/2023 15:32 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Suzuki	Model	Swift
Engine Type			
License Plate Number	SJP8676U	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$2000.00 with 3 days for repair

Insurlogic 5 (05/02/2023 15:31)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER		1	800.00	0.00 %	800.00
REAR BUMPER LOWER LID		1	400.00	0.00 %	400.00
Parts Subtotal					1,200.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER CORBON		1.0	300.00	0.00 %	300.00
REAR NUMBER PLATE		1.0	25.00	0.00 %	25.00
REAR BUMPER CLIPS		1.0	15.00	0.00 %	15.00
REVERSE SENSOR		1.0	220.00	0.00 %	220.00
STICKERS		1.0	200.00	0.00 %	200.00
Materials Subtotal					760.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	400.00	0.00 %	400.00
TUFF COAT	RnR	20.00	0.00 %	20.00
RNR REVERSE SONSORS	RnR	40.00	0.00 %	40.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 460.00

Paint Labor Subtotal 400.00

Labor Subtotal 860.00

Summary

Repair Cost 2,820.00

Discount(29 %) (820.00)

2,000.00

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,000.00