





55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0747/2022/EQ  
DATE : 30-Aug-22  
WIP : 39593

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/9/2022.  
YOUR INSURED VEH NO : SCZ 103 P

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept

OWNER'S NAME : MR. MANMINDER SINGH  
ADDRESS : 40 CANBERRA DRIVE  
#04-01  
SINGAPORE 768433  
TELEPHONE : HP +65 96730511  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2070037029  
VEHICLE NO : SMS 8783 S  
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC  
MODEL YEAR : 19/3/2020  
ENGINE NO : CZD 890997  
CHASSIS NO : WAUZZZF35L1068292  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 27-Aug-22  
PLACE OF ACCIDENT : EXIT SLIP ROAD TO PIE (KPE TUNNEL)



55 UBI ROAD 1, SINGAPORE 408689  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8783 S**

| S/N                             | NATURE OF JOBS                                                                                                                                       |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                               | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                    | S/N \$ | 360.00               | ✓                             |
| 2                               | TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.                                         | S/N \$ | 480.00               | ✓                             |
| 3                               | TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.                                                                                          | S/N \$ | 480.00               | ✓                             |
| 4                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.                                                                                                           | S/N \$ | 400.00               | ✓                             |
| 5                               | TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN                                                                                                  | S/N \$ | 200.00               | 150                           |
| 6                               | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 2,800.00             | 1000                          |
| <b>SUB-TOTAL LABOUR CHARGES</b> |                                                                                                                                                      | :      | <b>\$ 4,720.00</b>   |                               |

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8783 S**

| S/N                  | NATURE OF JOBS                                             | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|----------------------|------------------------------------------------------------|----------------------|-------------------------------|
| 7                    | TO RESPRAY REAR BUMPER, REAR LID AND REAR END<br>PANELLING | \$ 3,000.00          | <del>1100</del> 1650          |
| 8                    | TO CARRY OUT DIAGNOSTIC CHECK.                             | S/N \$ 192.00        | /                             |
| TOTAL LABOUR CHARGES |                                                            | : \$ 7,912.00        |                               |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8783 S

|                       |                                                   |     | DAMAGED PARTS & PRICES |           |
|-----------------------|---------------------------------------------------|-----|------------------------|-----------|
| S/N                   | PARTS DESCRIPTION                                 | QTY | S/NETT                 | REMARKS   |
| 1                     | REAR BUMPER <i>Rehnd</i>                          | 1   | \$ 1,958.00            | ✓ 1566.40 |
| 2                     | REAR BUMPER SPOILER <i>Rehnd</i>                  | 1   | \$ 510.00              | ✓ 408.00  |
| 3                     | REAR BUMPER TOW EYE COVER <i>new</i>              | 1   | \$ 48.00               | +         |
| 4                     | REAR BUMPER BRACKET <i>new</i>                    | 1   | \$ 53.00               | +         |
| 5                     | REAR BUMPER REFLECTOR - LH / RH <i>new LH cut</i> | 2   | \$ <del>92.00</del>    | 46 36.48  |
| 6                     | REAR INNER TAIL LIGHT - LH / RH <i>new</i>        | 2   | \$ 2,060.00            | +         |
| 7                     | REAR INNER TAIL LIGHT TRIM - LH / RH <i>new</i>   | 2   | \$ 68.00               | +         |
| 8                     | REAR LICENCE PLATE <i>new</i>                     | 2   | \$ 113.00              | +         |
| 9                     | REAR BUMPER AERIAL ACCESS KEY <i>new</i>          | 1   | \$ 79.00               | +         |
| 10                    | REAR BOOT LID CONTROL UNIT <i>new</i>             | 1   | \$ 484.00              | +         |
| 11                    | REAR BUMPER CARRIER <i>Dented.</i>                | 1   | \$ 693.00              | ✓ 554.40  |
| 12                    | REAR BUMPER HOLDING STRAP - LH / RH <i>new</i>    | 2   | \$ 64.00               | +         |
| 13                    | REAR PARKING AID SENSOR <i>new</i>                | 3   | \$ 797.00              | +         |
| 14                    | REAR PARKING AID SEAL RING <i>new</i>             | 4   | \$ 10.00               | +         |
| 15                    | REAR WHEEL COVER - LH / RH <i>new</i>             | 2   | \$ 566.00              | ✓ 452.00  |
| 16                    | REAR LID <i>Dented</i>                            | 1   | \$ 3,767.00            | ✓ 3013.60 |
| 17                    | PACKING ADHESIVE <i>new</i>                       | 1   | \$ 21.00               | ✓ 16.80   |
| 18                    | REAR LID HINGE - LH / RH <i>new</i>               | 2   | \$ 331.00              | +         |
| 19                    | REAR LID ATTACHMENT PARTS <i>new</i>              | 1   | \$ 393.00              | +         |
| 20                    | REAR LID LOCK <i>new</i>                          | 1   | \$ 293.00              | +         |
| SUB TOTAL SPARE PARTS |                                                   | :   | \$ 12,400.00           |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6356 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8783 S

|                      |                                                 |     |              | DAMAGED PARTS & PRICES |  |
|----------------------|-------------------------------------------------|-----|--------------|------------------------|--|
| S/N                  | PARTS DESCRIPTION                               | QTY | S/NETT       | REMARKS                |  |
| 21                   | REAR LID LOCK COVER <i>Neu</i>                  | 1   | \$ 8.00      | <i>x</i>               |  |
| 22                   | REAR LID SERVMOTOR <i>Neu</i>                   | 1   | \$ 298.00    | <i>x</i>               |  |
| 23                   | REAR LID BOWDEN CABLE <i>Neu</i>                | 1   | \$ 43.00     | <i>x</i>               |  |
| 24                   | REAR LID STRIKER PLATE <i>Just ne</i>           | 1   | \$ 74.00     | <i>x</i>               |  |
| 25                   | REAR LID FLAP GASKET                            | 1   | \$ 229.00    | <i>x</i>               |  |
| 26                   | REAR LID CAMERA <i>could</i>                    | 1   | \$ 1,478.00  | <i>1182.40</i>         |  |
| 27                   | REAR LID HOLE PLUG <i>green</i>                 | 4   | \$ 133.00    | <i>x</i>               |  |
| 28                   | REAR LID STOP BUFFER                            | 2   | \$ 61.00     | <i>x</i>               |  |
| 29                   | AUDI EMBLEM <i>Just ne</i>                      | 1   | \$ 144.00    | <i>114.80</i>          |  |
| 30                   | "Q3" INSCRIPTION                                | 1   | \$ 104.00    | <i>82.80</i>           |  |
| 31                   | REAR WINDOW <i>Neu</i>                          | 1   | \$ 1,064.00  | <i>851.20</i>          |  |
| 32                   | WINDOW PRIMER <i>Neu</i>                        | 1   | \$ 22.00     | <i>17.36</i>           |  |
| 33                   | REAR LID SPOILER - LH / RH <i>Neu</i>           | 2   | \$ 470.00    | <i>375.20</i>          |  |
| 34                   | REAR LID SPOILER GASKET CLIP - UPPER <i>Neu</i> | 2   | \$ 16.00     | <i>12.64</i>           |  |
| 35                   | REAR LID TRIM PANEL - LOWER <i>Pays</i>         | 1   | \$ 541.00    | <i>x</i>               |  |
| 36                   | REAR CROSS PANEL TRIM <i>Neu</i>                | 1   | \$ 213.00    | <i>x</i>               |  |
| 37                   | REAR NO PLATE <i>Neu</i>                        | S/N | \$ 60.00     | <i>x</i>               |  |
| 38                   | REAR WINDSCREEN SEALANT <i>Neu</i>              | S/N | \$ 200.00    | <i>200.00</i>          |  |
| 39                   | SUNDRIES <i>Neu</i>                             |     | \$ 400.00    | <i>35.86</i>           |  |
| TOTAL SPARE PARTS    |                                                 | :   | \$ 17,958.00 |                        |  |
| TOTAL LABOUR CHARGES |                                                 | :   | \$ 7,912.00  |                        |  |
| GRAND TOTAL          |                                                 | :   | \$ 25,870.00 |                        |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6341 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*  
SURVEYED DATE : *01/09/22*  
AUTHORISED DATE : *St.L.*  
EXCESS COST : *07 Days*  
LIABILITY : *Not Authorised, 84 Days*  
REMARKS :

## PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

*Asher.*

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.  
Date  
Service Advisor  
Pages  
Regn No  
Model No

PA/TP/0747/2022/EQ  
21-Sep-22  
CHANG  
1 of 1  
SMS 8783 S  
AUDI Q3 1.4 TFSI

| Quantity       | Description                                                                                                                    | Unit Price | Amount                      |
|----------------|--------------------------------------------------------------------------------------------------------------------------------|------------|-----------------------------|
| <u>Labours</u> |                                                                                                                                |            |                             |
| 1              | TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. | S/N        | S 1,600.00 ✓                |
| 2              | TO CUT OUT AND WELD REAR END PANELLING.                                                                                        |            | S <del>2,000.00</del> 1000. |
| <u>Parts</u>   |                                                                                                                                |            |                             |
| 1              | REAR END PENAL - OUTER <i>Pented.</i>                                                                                          | 1          | S 329.00 ✓ <i>262.80</i>    |
| 2              | REAR LID BUNGS <i>nee</i>                                                                                                      | 4          | S 133.00 ✓ <i>105.92</i>    |
| 3              | REAR LID CLIP <i>ntc.</i>                                                                                                      | 3          | S 68.00 ✓ <i>54.00</i>      |
| 4              | ACRYLIC SEALER <i>nee</i>                                                                                                      | S/N        | S 180.00 ✓ <i>180.00</i>    |
| 5              | CAVITY WAX <i>nee</i>                                                                                                          | S/N        | S 140.00 ✓ <i>140.00</i>    |
| 6              | STONE CHIP <i>nee</i>                                                                                                          | S/N        | S 180.00 ✓ <i>180.00</i>    |
| 7              | METAL FILLER POWDER <i>nee</i>                                                                                                 | S/N        | S 280.00 ✓ <i>280.00</i>    |
| GRAND TOTAL    |                                                                                                                                |            | \$ 4,910.00                 |

*Resinged Admin* For Premium Automobiles Pte Ltd

*fls.*

Add 2 days for the replacement of the Rear End Panel.

*fls.*



Authorized Signature