Our Ref:	GBC6549E220823		Date: 11/09/2022
Your Ref:			
3 Anson F Springleat Singapore	ping Insurance (Singapore) Pte Ltd Road #16-00 f Tower e 079909 tor Claims Department		
Dear Sir /	' Madam		
	ccident Along Open Space Carpark Near Verdun Road GBC6549E and GBK4550X On 23/08/2022		
m/vehicle by "Chi for S\$_1,6	oldbell Leasing Pte Ltd (NRIC / ROC No: 19900119 e - GBC6549E at all material times of the above accided na Taiping authorized appraiser and we/I based our/1600-00 being the repair for 02 Days (Strictly on a Water ascertained that you were the insurers of the driver of materials.)	ent. Our my clain ithout P	r/my vehicle was surveyed ns on his recommendation rejudice Basis).
	s involved in the aforesaid accident with our/my m/vehicle		
solely by	ereby you are the insurers of m/vehicle GBK4550X and the negligence of your insured and as a result there of our red loss and damage as follows:		
LOU Fee	epairs ore-repair notice 02 days @ S\$ <u>80-00 [2982 cc]</u> for <u>02</u> days @S\$ <u>80-00 [2982 cc]</u> e Invoice No:	S\$	1,600-00 160-00 160-00
	A search fee lee (Cash Sale No) lee		2-00
Total Am	ount	S\$	1,922-00
We/I enc (i) (ii)	lose herewith copies of the supporting documents for vehic Motor Accident Report & Documents; Repair Invoices;	cle no. <u>(</u>	GBC6549E as follows:-
Kindly loo as possib	ok into the matter and let us/me hear from you on the set le.	tlement	of our/my claims as soon
	mit us/me your settlement sum in favor of M/s Liu's Bro the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay (		
Thank yo	u.		
Yours fait	thfully,		
Messers (	er of m/vehicle <u>GBC6549E</u> Goldbell Leasing Pte Ltd Bro Auto Engineering Workshop		

## Liu's Brother Auto Engineering Workshop No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

liusbro@ymail.com **UEN No: 53291793**J

Tel: 67411730

07-09-2022

Manual

FINAL BILL

Name: China Taiping Insurance (Singapore) Pte Ltd

Address Motor Claims Department 3 Anson Road #16-00

> Springleaf Tower Singapore 079909

Ref Date: Ref No: Vehicle No:

GBC6549E220823 GBC6549E

Model / Make: Toyota Hiace Capacity: 2982 cc

Item #	Damaged Area	Description	Unit Price		Qty	Estimation / Quotation		N / SN	Cost Of Repair	
$\frac{1}{2}$	Rear	Tailgate Tailgate "TOYOTA Logo" Motif	\$ \$	2,050.00 70.50	1	\$ \$	2,050.00 70.50		\$ \$	-
3 4		Tailgate "70 KM/H" Sticker Tailgate "8 PAX" Sticker	\$ \$	15.00 15.00	1	\$	15.00 15.00	SN	\$ \$	-
6		"Corporate" Advertisement & Artwork Remove & reinstall Windscreen Glass to facilitate repairs & perform water test				\$	200.00 120.00	SN	\$	-
7		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs				\$	200.00		\$	-
8		To putty & spray painting & including touch up paint on accident affectedd areas				\$	300.00		\$	-
9		To apply Rust Proofing , reseal tuff-coating treatment on accident area				\$	30.00		\$	-

Total Parts & Labour of estimate for damaged vehicle

Total amount in Lumpsum Basis for repaired vehicle

One Thousand Six Hundred Only

SDL

\$ 3,000.50



1,600.00

Liu's Bro Auto Engrg Wks

**INSURER ENQUIRY** 

Find insurer Vehicle reg. no.

GBK4550X

**Date of Accident** 

23/08/2022

Reset

## % RESULT & RECEIPT

## **TP Insurer Enquiry**

**Payment details** 

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13** 

Total Amount Due (GST Inclusive): \$\$2

**General Insurance Association** 

Records Management Centre GST Registration No: **M400017735**