

Not Notched
Pehong B4 perap

8761638

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P

AAD2208-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 AUG 2022

SHB9926P

JTDBK3FU903091430

200303878K

TOYOTA

PRIUS GEN 4

24/08/2022

YN9444Z/ China-

31/08/2020

PART	
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB- ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	COVER, REAR BUMPER, LOWER
1	COVER, DECK TRIM, REAR
1	MOULDING SUB-ASSY, ROOF TOP
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	SPOILER SUB-ASSY, REAR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	BOX, DECK FLOOR, REAR
1	BOX, DECK FLOOR, RH
1	BOX, DECK FLOOR, LH
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

LIST	
\$	Bu 485.60 —
\$	Bu 332.70 —
\$	CM 374.50 —
\$	Ln 118.30 X
\$	Ln 118.30 X
\$	Dit 132.60 —
\$	Mit 22.00 —
\$	Ln 126.70 X
\$	Mit Mit 656.90 car 2
\$	Mit Bu 54.40 X
\$	Mit Bu 54.40 X
\$	Bu 651.00 2
\$	Bu 1,147.80 —
\$	CM Mit 1,575.40 —
\$	Ln 54.60 —
\$	Ln 54.60 —
\$	Ln 47.90 —
\$	CM 913.60 —
\$	Ln 259.20 X
\$	Ln 372.30 X
\$	Ln 105.80 X
\$	Ln 313.60 X
\$	Ln 313.00 X
\$	Ln 242.50 X
\$	Ln 242.50 X
\$	Ln 61.00 X
\$	Ln 61.00 X

TOTAL \$ 8,892.20
25% \$ 2,223.05

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P**AAD2208-**

		\$	6,669.15	
Special Nett				
1	REAR SPOILER CLIP	\$	na 65.00	✓
1	REAR BUMPER SIDE CLIP	\$	na 60.00	✓
1	BOOT STICKER TRANSCAB	\$	na 100.00	30sn ✓
1	BOOT STICKER TEL NO	\$	na 100.00	30sn ✓
1SET	PARKING AID	\$	sn 700.00	X
1SET	REAR BUMPER CLIP	\$	na 85.00	X
1	REAR BUMPER RETAINER CLIP	\$	na 75.00	X
TOTAL		\$	1,120.00	
TOTAL PARTS		\$	7,789.15	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	8001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P**AAD2208-**

TOTAL	\$	5,300.00
--------------	-----------	-----------------

Over All Total	\$	13,089.15
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~20~~ Days

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9926P**AAD2208-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB9926P

JTDKB3FU903091430

200303878K

TOYOTA

PRIUS **GEN 4**

24/08/2022

YN9444Z/

31/08/2020

SUPPLEMENTARY**PART**

- 1 LENS & BODY, REAR COMBINATION LAMP, RH (Upper)
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)
- 1 COVER, REAR COMBINATION LAMP, RH

LIST

CM	339.6	—
CM	261	—
CM	69.9	—

TOTAL	\$	670.50
25%	\$	167.63
	\$	502.88

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To
Facilitate Bodywork Repair.

\$	300.00	180/-
----	--------	-------

TOTAL	\$	300.00
--------------	-----------	---------------

Over All Total	#REF!
-----------------------	--------------