

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1376Z

DATE 25.08.2022

MAKE REG.19.12.2019

MODEL : HYU IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH / cut			\$35.00
1	FRONT BUMPER / Re			\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING X NN			\$368.50
1	FRONT BUMPER GRILLE LH / SCR			\$186.50
1	FRONT DAY LIGHT LH X an			\$642.50
1	FRONT FENDR SHIELD LH / Re			\$164.70
1	FRONT FENDER LH / Bue			\$588.80
1	FRONT FENDER EMBLEM / Re			\$26.60
1	FRONT WING MIRROR LH / cut			\$1,391.70
1	HEAD LAMP LH / cut			\$2,110.30
1	FRONT WHEEL COVER LH / cut			\$364.40
	SUB TOTAL			\$6,360.10
	20.00%			\$1,272.02
	DISCOUNTED TOTAL			\$5,088.08
1	FRONT DOOR COMFORT LOGO STICKER / M.C.			\$75.00
				\$67.50
	Labour Charge			
	Panel Beating			\$850.00
	Spray Paint			\$800.00
	Reset Wheel alignment			\$60.00
	Check lighting			\$60.00
	Towing Fee			\$60.00
	TOTAL LABOUR			\$1,830.00
	ESTIMATE TOTAL			\$6,918.08
	5 Days.			
	4/5			
	Gmo Qit			
	26/8/22			
	423 pm			
	LKK Auto Consultants hence notify the Repairer of the following: • To reserve a place for the painting • To replace the damaged parts • To provide a written estimate • To provide a written estimate on a "best" basis • To provide a written estimate on a "best" basis • To provide a written estimate on a "best" basis Acknowledged by: _____ Signed by: _____ Date: _____			-20%: 4700
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				