

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : OD/082022/5594
Date : 25-08-2022
Accident Date : 23-08-2022

Vehicle Details

Make & Model : Mercedes Benz GLC300 AMG
LINE 4MATIC AUTO
Chassis No : W1N2539842V248759
Registration No : SMX909Z

S/N	Description	Qty	Amount (S\$)
1	TO REPAIR REAR LH TAILLAMP PANEL	1.00	\$150.00 100
2	TO SPRAY PAINT REAR LH TAILLAMP PANEL	1.00	\$180.00 100

Subtotal w/o GST: \$330.00

Paul
01/09/22

Issued by Raymond Teo

This is a computer-generated document. No signature is required.