

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : OD/082022/5594
Date : 25-08-2022
Accident Date : 23-08-2022

Vehicle Details

Make & Model : Mercedes Benz GLC300 AMG
LINE 4MATIC AUTO
Chassis No : W1N2539842V248759
Registration No : SMX909Z

S/N	Description	Qty	Amount (\$)
1	LH TAILLAMP <i>cm</i>	1.00	\$380.00
2	LH TAILGATE REFLECTOR <i>sm X</i>	1.00	\$380.00
3	REAR BUMPER <i>de</i>	1.00	\$550.00
4	REAR BUMPER LH REFLECTOR <i>sm</i>	1.00	\$30.00
5	REAR BUMPER CENTRE PAD <i>sm</i>	1.00	\$480.00
6	REAR BUMPER LH SIDE RETAINER ?	1.00	\$110.00
7	REAR BUMPER LH PARKING SENSOR <i>sm</i>	1.00	\$120.00

\$2,050.00

Margin: 10%

\$205.00

\$2,255.00

8 TO REPAIR DAMAGES

1.00

~~\$380.00~~ 250

9 TO SPRAY PAINTING

1.00

~~\$480.00~~ 250

Subtotal w/o GST:

\$3,115.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.

Resu
Hp 9001 0068
3 days
P/P
30/08/22 P1410
EXCESS: TRA
Revert
Resu before paint