



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM22008401/Gcy3e2 Date: 07/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9881P	Veh. Inspected	SNF 5604C
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M049VH	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	29/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	BYD E6	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	LC0CE4DC9N0036924	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	CHAO YANG	6 mm
	L/H Front Tyre	215/55 R17	CHAO YANG	6 mm
	R/H Rear Tyre	215/55 R17	CHAO YANG	6 mm
	L/H Rear Tyre	215/55 R17	CHAO YANG	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/08/2022	Inspection Date	30/08/2022
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	