

# CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 000/ Email: info@carsmith.biz

VEHICLE NO: SNF5604C

MAKE & MODEL: BYD E6

DOA: 29.08.2022

CLAIM TYPE: TP CLAIM

## ESTIMATION QUOTE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| PARTS                        | QTY | PRICE (\$)  | REMARKS     |
|------------------------------|-----|-------------|-------------|
| REAR BUMPER TOP              | 1   | \$ 1,405.00 | ✓           |
| REAR BUMPER BOTTOM           | 1   | \$ 1,380.00 | 650         |
| REAR BUMPER RETAINER LH      | 1   | \$ 87.00    |             |
| REAR BUMPER BRACKET LH       | 1   | \$ 87.00    |             |
| REAR BUMPER RETAINER RH      | 1   | \$ 87.00    |             |
| REAR BUMPER BRACKET RH       | 1   | \$ 87.00    |             |
| REAR REFLECTOR LH            | 1   | \$ 198.00   | 95          |
| REAR REFLECTOR CENTRE        | 1   | \$ 425.00   | 335         |
| REAR BUMPER LOWER GARNISH    | 3   | \$ 750.00   | 440         |
| REAR BUMPER INNER BRACKET LH | 1   | \$ 259.00   |             |
| REAR END PANEL               | 1   | \$ 852.00   |             |
| REAR END PANEL REINFORCEMENT | 1   | \$ 565.00   | 450         |
| BOOTLID                      | 1   | \$ 3,750.00 |             |
|                              |     | \$ 9,932.00 | 3375        |
|                              |     | LESS 10%    | \$ 993.20   |
|                              |     | SUB TOTAL   | \$ 8,938.80 |

| SPECIAL NETT ITEMS         | QTY   | PRICE (\$) | REMARKS     |
|----------------------------|-------|------------|-------------|
| REAR BUMPER CLIP           | 1 SET | \$ 80.00   | X           |
| REAR REVERSE SENSOR        | 1     | \$ 485.00  | 200         |
| REAR REVERSE SENSOR WIRE   | 1     | \$ 580.00  | 300         |
| REAR REVERSE SENSOR HOLDER | 1     | \$ 80.00   | X           |
|                            |       | SUB TOTAL  | \$ 1,225.00 |
|                            |       |            | 500         |

| LABOUR                                           | QTY | PRICE (\$)  | REMARKS     |
|--------------------------------------------------|-----|-------------|-------------|
| CHECK REAR WIRING AND LIGHTING SYSTEM            | 1   | \$ 150.00   | X           |
| DIAGNOSE CHECK ON REVERSE SENSOR                 | 1   | \$ 400.00   | X           |
| REMOVE AND RENEW REAR REVERSE SENSOR             | 1   | \$ 120.00   | 40          |
| PANEL BEATING ON AFFECTED AND RENEW DAMAGE PARTS | 1   | \$ 1,600.00 | 400         |
| SPRAY PAINTING ON AFFECTED AREAS                 | 1   | \$ 1,600.00 | 400         |
| APPLY ANTI RUST ON AFFECTED AREAS                | 1   | \$ 100.00   | X           |
|                                                  |     | SUB TOTAL   | \$ 3,970.00 |
|                                                  |     |             | 840         |

4377.5

-20%: 3500