



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 2976D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,425.00	-
2	FRONT BUMPER SIDE HOLDER - LH / RH @\$28.00	NOT NECESSARY	56.00	-
10	FRONT BUMPER CLIPS @\$10.00	NOT NECESSARY	100.00	-
1	FRONT FENDER - LH	TO REPAIR SEE LABOUR	1,015.00	-
10	FRONT FENDER COWLING CLIPS - LH @\$10.00	NOT NECESSARY	100.00	-
1	FRONT FENDER CHROME - LH	NOT NECESSARY	46.00	-
	LESS 10% DISCOUNT		-274.20	-
			2,467.80	-
	<b><u>LABOUR</u></b>			
	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER - LH.		500.00	200.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		600.00	400.00
	TO CHECK WIRING.	NOT NECESSARY	40.00	-
	TO TUFF KOTE.	NOT NECESSARY	60.00	-
			1,200.00	600.00
	<b>GRAND TOTAL</b>		<b>3,667.80</b>	<b>600.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>600.00</b>

Report Ref No. CS/FCI22008402/Uqy3e2

MARKET VALUE: \$92,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$56,792.00=NETT VALUE: \$35,208.00

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.