

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008406/AVCM4**Date:** 15/12/2022**REFERENCE**

Insured/Claimant: LIM BOON LEONG Policy No:
Date of Loss: 23/08/2022 Nature of Claim: OD Claim No: 1057233109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5338E**
Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK084478
Reg. Date: 30/09/2019 (Man. Year: 2019) Chassis No: WAUZZZF45KA090025
Colour: Blue Odometer: 49144 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$143,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 12,256.00 | 7,488.88 | 4,767.12 | 38.90 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,332.00 | 2,932.00 | 3,400.00 | 53.70 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 18,588.00 | 10,420.88 | 8,167.12 | 43.94 |
| - Excess (S\$) | 100.00 | 100.00 | 0.00 | 0.00 |
| (S\$) | 18,488.00 | 10,320.88 | 8,167.12 | 44.18 |
| + GST 7.00/7.00% (S\$) | 1,294.16 | 722.46 | 571.70 | 44.18 |
| Nett Amount (S\$) | 19,782.16 | 11,043.34 | 8,738.82 | 44.18 |

INSPECTION

Date of Assignment: 30/08/2022
Date Inspected: 29/08/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 3,188.00 FS | *2,550.40 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 487.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER SECURING STRIPS | Necessary | 249.00 FS | *198.80 FS |
| 4 | 1 | | *REAR BUMPER SPOILER | Cut | 276.00 FS | *220.80 FS |
| 5 | 1 | | *REAR BUMPER BLACK TRIM | Cracked | 326.00 FS | *260.80 FS |
| 6 | 2 | | *REAR BUMPER BRACKET LH / RH | Not Necessary | 260.00 FS | *- FS |
| 7 | 2 | | *REAR BUMPER LIGHT REFLECTOR REAR LH /RH | Not Necessary | 92.00 FS | *- FS |
| 8 | 1 | | *REAR BUMPER REINFORCEMENT BEAM | Dented | 1,131.00 FS | *904.80 FS |
| 9 | 2 | | *REAR BUMPER SEAL | Necessary | 32.00 FS | *25.28 FS |
| 10 | 2 | | *REAR BUMPER GUIDE SECTION LH/ RH | Not Necessary | 52.00 FS | *- FS |
| 11 | 2 | | *REAR BUMPER HOLDING STRIPS LH / RH | Not Necessary | 188.00 FS | *- FS |
| 12 | 1 | | *REAR PARKING AID SENSORS INNER/ OUTER 2PCS | Inner Missing | 531.00 FS | *212.00 FS |
| 13 | 4 | | *REAR PARKING AID SENSORS SEAL RINGS | Necessary | 10.00 FS | *8.00 FS |
| 14 | 2 | | *EXHAUST TAIL TRIM PIPE LH / RH | Not Necessary | 766.00 FS | *- FS |
| 15 | 1 | | *REAR LID | Dented | 3,497.00 FS | *2,797.60 FS |
| 16 | 1 | | *REAR LID LOCK | Not Necessary | 218.00 FS | *- FS |
| 17 | 1 | | *REAR LID LOCK COVER CAP | Not Necessary | 8.00 FS | *- FS |
| 18 | 1 | | *REAR LID LOCK STRIKER | Not Necessary | 37.00 FS | *- FS |
| 19 | 1 | | *PARKING ADHESIVE | Necessary | 21.00 FS | *16.80 FS |
| 20 | 1 | | *REAR LID WEATHERSTRIP | Not Necessary | 229.00 FS | *- FS |
| 21 | 1 | | *AUDI CHROME LOGO | Necessary | 144.00 FS | *114.80 FS |
| 22 | 1 | | *AUDI CHROME EMBLEM A4 | Necessary | 104.00 FS | *82.80 FS |
| 23 | 1 | | *REAR NO PLATE | Dented | 60.00 FS | *60.00 FS |
| 24 | 1 | | *SUNDRIES | Necessary | 350.00 FS | *36.00 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|------------------|-----------------|
| Total Parts (\$\$) | 12,256.00 | 7,488.88 |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS | New | 280.00 | 280.00 |
| 3 | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 2,500.00 | 1,000.00 |
| 4 | TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING | New | 3,000.00 | 1,100.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (S\$) | | | 6,332.00 | 2,932.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >